



CÓDIGO TSM	DATO TÉCNICO	NÚMERO DE PARTE	MODELO
TSM-BP-BW1-2	PERKINS		B1G
TSM-BP-BW2-1B	POWER STROKE GRANDE		B2
TSM-BP-BW4-1	PERKINS	1200-152-300	B2
TSM-BP-BW6-1B	MERCEDES BENZ	1855-970-0002 1855-970-0010	B03G
TSM-BP-BW7-1	BMW N55	1853-970-0000 1853-970-0003	B03 / B03G
TSM-BP-C1-1B	CZ C15-505	399-0015-505 03825301AG	C12 / C14
TSM-BP-G1-1	PERKINS FASE 2 / FASE 4 Y MAS	408045-0012	T04B T04B58
TSM-BP-G1-2	VOLVO	409629-0008	TA34 TB34 T04B
TSM-BP-T300	JOHN DEERE TRACTOR 350 / JOHN DEERE TRACTOR 4093T	409629-0008 446311-0002 RE59379 471049-0003 446311-0006	T300

<b>TSM-BP-T350</b>	<b>JOHN DEERE 6068T</b>	<b>409629-0008 471050-0005 RE503635</b>	<b>T350</b>
<b>TSM-BP-G3-2</b>		<b>409629-0002</b>	<b>TA31</b>
<b>TSM-BP-G3-3</b>		<b>409629-0001</b>	<b>TA31</b>
<b>TSM-BP-G3-4</b>	<b>PERKINS, JONH DEERE Y MÁS</b>	<b>409629-0004</b>	<b>TB03 TA31 TB31 Y MAS</b>
<b>TSM-BP-G4-1</b>	<b>M.B OM366 / NAVISTAR</b>	<b>408045-0030</b>	<b>TBP4 T04E66 T04E17</b>
<b>TSM-BP-G8-1</b>	<b>NEW HOLLAND APLICA VARIOS</b>		<b>T28</b>
<b>TSM-BP-G9-1</b>	<b>PLATO O AUMENTO (ADAPTADOR)</b>		<b>TB28 Y MAS</b>
<b>TSM-BP-G9-3</b>	<b>PLATO AUMENTADO (ADAPTADOR)</b>	<b>SE COMPRA PARA REVISAR QUE SEA COMPATIBLE CON CHRA GT25-002</b>	
<b>TSM-BP-G11-7</b>	<b>HINO PERKINS</b>	<b>480301-0001 479016-0001</b>	<b>GT3576</b>

<b>TSM-BP-G12-4</b>	<b>NAVISTAR NGD GRANDE DE PORTANILLO</b>	<b>751400-0001</b>	<b>GT37 GT40</b>
<b>TSM-BP-G12-5</b>	<b>NAVISTAR NGD CHICO DE PORTANILLO</b>	<b>751361-0001</b>	<b>GTA3782D</b>
<b>TSM-BP-G14-2</b>	<b>VOLVO</b>	<b>725273-0004</b>	<b>GT45 GTA45 GTA4594</b>
<b>TSM-BP-G22-1</b>	<b>FORD POWER STROKE 6.0L</b>	<b>743250-0004</b>	<b>GT37VAS GTA3782V</b>
<b>TSM-BP-G22-3</b>	<b>DURAMAX LLY 6.6L GMC</b>	<b>8973525645 736554-0011</b>	<b>GT37-VAS</b>
<b>TSM-BP-G24-1</b>	<b>CATERPILLAR C12/ S.60 DD4 12.7L</b>	<b>GTA4294</b>	<b>GTA42</b>
<b>TSM-BP-G29-1</b>	<b>DETROIT DIESEL TRUCK SERIE 60 DDEC5</b>	<b>758160-0006 730395-0035 720191-0086</b>	<b>GTA4502V</b>
<b>TSM-BP-G33-1</b>	<b>FORD POWER STROKE 7.3L</b>	<b>702011-0008</b>	<b>GTP38R</b>
<b>TSM-BP-G33-2</b>	<b>FORD POWER STROKE 7.3L</b>	<b>702012-0006</b>	<b>GTP38R</b>

<b>TSM-BP-G34-1</b>	<b>NAVISTAR NGD ESPACIADOR GRANDE</b>	<b>751359-0001 PARA</b>	<b>GTA3782 GT40</b>
<b>TSM-BP-G34-2</b>	<b>NAVISTAR NGD DE ESPACIADOR PLATO CHICO</b>	<b>729161-0001 PARA</b>	<b>GTA3782 GT40</b>
<b>TSM-BP-GT003</b>	<b>AUDI</b>	<b>701335-0003</b>	<b>GT2052V</b>
<b>TSM-BP-GT005</b>	<b>PERKINS, CATERPILLAR</b>	<b>721086-0001</b>	<b>GT2556S</b>
<b>TSM-BP-GT005-1</b>	<b>FORD Y MAS</b>	<b>703682-0057</b>	<b>GT2556S</b>
<b>TSM-BP-GT007</b>		<b>436466-0002</b>	<b>GT2052S</b>
<b>TSM-BP-GT016</b>	<b>PERKINS, CAT</b>		<b>GT2560S GT2259 GT2260V</b>
<b>TSM-BP-GT016-1</b>	<b>PERKINS, CAT Y MAS</b>		<b>GT2260V GT2560</b>
<b>TSM-BP-GT019</b>	<b>PORTANILLO CHICO</b>	<b>434689-0002</b>	<b>GT2052S</b>
<b>TSM-BP-GT022</b>	<b>SPRINTER MODULO</b>	<b>434820-0002 434820-0003 434820-0011 703682-0043</b>	<b>GT2056</b>
<b>TSM-BP-GT027</b>	<b>PERKINS CATERPILLAR</b>	<b>721085-0001</b>	<b>GT2052S</b>

<b>TSM-BP-GT027-1</b>		<b>721085-0001</b>	<b>GT2052</b>
<b>TSM-BP-GT029</b>	<b>HYUNDAI H100</b>	<b>433294-0002</b>	<b>GT1749S</b>
<b>TSM-BP-GT030-3</b>	<b>HINO TRUCK DUTRO N04C</b>	<b>779144-0023</b>	<b>GTB2056LV GTB2263KLN</b>
<b>TSM-BP-GT033</b>	<b>HINO TRUCK DUTRO N04C</b>	<b>783801-0029</b>	<b>GTB2260V</b>
<b>TSM-BP-GT038</b>	<b>FORD TRANSIT DE GEOMETRIA</b>	<b>763470-0004</b>	<b>GTB1749V</b>
<b>TSM-BP-GT039</b>	<b>EUROVAN 1.9 TDI</b>	<b>751851-0002</b>	<b>GT1646V</b>
<b>TSM-TSP-GT32-1</b>	<b>POWER STROKE 6.7 SET FLECHA PROPELA BALERO ANILLOS PORTANILLO</b>	<b>GARRETT UNA PROPELA</b>	<b>GT32</b>
<b>TSM-BP-H1-1</b>	<b>CUMMINS VARIOS GRANDE</b>	<b>3522801</b>	<b>H1C H1E WH1C</b>
<b>TSM-BP-H3-1</b>	<b>CUMMINS VARIOS</b>	<b>3530923</b>	<b>HX35 HX40</b>
<b>TSM-BP-H4-1</b>	<b>CUMMINS VARIOS</b>	<b>3590044</b>	<b>HX50 HX55</b>
<b>TSM-BP-H5-1B</b>	<b>CUMMINS L10</b>	<b>3762564</b>	<b>H2C H2D</b>

<b>TSM-BP-H6-1</b>	<b>CUMMINS 4BT PLATO CHICO</b>	<b>3534947</b>	<b>H1C</b>
<b>TSM-BP-H11-1</b>	<b>IVECO TRUCK CUMMINS ISX VALV. MECANICA Y MAS</b>	<b>4034048</b>	<b>HY55V HE551V</b>
<b>TSM-BP-H11-1-2</b>	<b>S.60 DD6 DE ACTUADOR ELECTRONICO / VALVULA MECANICA ISM</b>	<b>4032255</b>	<b>HE531VE HE531V</b>
<b>TSM-BP-H11-1-3</b>	<b>CUMMINS ISX EGR 450HP</b>	<b>3774612</b>	<b>HE561VE HE500VG</b>
<b>TSM-BP-H12-1</b>	<b>DODGE RAM ISB 6.7L / PACCAR RX6</b>	<b>4046837</b>	<b>HE351VE HE300VG</b>
<b>TSM-BP-H13-1</b>	<b>CUMMINS ISL VALVULA MECANICA VOLVO</b>	<b>4045934</b>	<b>HE431VE HE400VG</b>
<b>TSM-BP-H13-5-1B</b>	<b>CUMMINS ISX (DE FIERRO)</b>	<b>3773561 3773562</b>	<b>HE431VE</b>
<b>TSM-BP-H13-7</b>	<b>CUMMINS ISC / ISM (DE ALUMINIO)</b>	<b>2836542 2881657</b>	<b>HE431VE</b>
<b>TSM-BP-H15-1B</b>	<b>CUMMINS 350 Y 400 N14</b>	<b>3527047</b>	<b>HT60 HT3B</b>
<b>TSM-BP-I1-1</b>	<b>FIAT PUNTO GT VL7</b>	<b>NN133021</b>	<b>RHB5</b>
<b>TSM-BP-I2-2</b>	<b>GMC CHEVROLET PICK-UP 6.5D</b>	<b>CM3 GM4 GM8</b>	<b>RHB6 RHC6</b>

<b>TSM-BP-I3-1</b>	<b>USO MARINO INDUSTRIAL</b>	<b>NH172501</b>	<b>RHB7/RHC7</b>
<b>TSM-BP-I6-10</b>	<b>M.B A-CLASS 250 W176 CLA-CLASS / M.B B-CLASS 2.0</b>	<b>A2740903580 A2740903080</b>	<b>RHF4 RHF4H</b>
<b>TSM-BP-I10-1</b>	<b>MITSUBISHI L200 Y MAS</b>		<b>RHF4</b>
<b>TSM-BP-I11-1</b>	<b>PLATO APLICA VARIOS</b>		<b>RHF3</b>
<b>TSM-BP-I11-2</b>	<b>VW, SEAT Y AUDI 1.2TSI Y MAS</b>	<b>03F145701</b>	<b>RHF3</b>
<b>TSM-BP-I13-1</b>	<b>M.B SPRINTER VITO</b>	<b>VA70 VL35 VL25 / VV14</b>	<b>RHF4</b>
<b>TSM-BP-I16-5</b>	<b>NISSAN FRONTIER, NAVARA 2.5 DI</b>	<b>VN3</b>	<b>RHF4</b>
<b>TSM-BP-I16-10</b>	<b>NISSAN NP300 / CABSTAR</b>	<b>VN4</b>	<b>RHF4</b>
<b>TSM-BP-I17-1</b>	<b>SMART, SUBARU, MITSUBISHI</b>	<b>VF30, VF35, VF37, VF39, VF43, VF48, VF52</b>	<b>RHF5</b>
<b>TSM-BP-I17-3</b>	<b>ISUZU NQR 75L</b>	<b>8980277725 VIFG VIFH VIET</b>	<b>RHF55 RHF55V</b>
<b>TSM-BP-I20-2</b>	<b>ISUZU ELF 200 / 300 3.0 TDI</b>	<b>8981115480</b>	<b>RHF5V</b>

<b>TSM-BP-I25-1</b>	<b>AUDI TT S3 2.0TSI VW MK7, IS38 BILLET</b>	<b>06K145722A</b>	<b>RHF5 JH5</b>
<b>TSM-BP-I25-2</b>	<b>AUDI A4, A5, A6 2.0L 2017 PROPELA BILLET IS20</b>	<b>06L145702M 06L145702P</b>	<b>RHF5 JH5</b>
<b>TSM-BP-K1-4</b>	<b>BORA / MINI / PEUGEOT</b>	<b>5304-151-5716</b>	<b>K03 K04</b>
<b>TSM-BP-K1-4-9</b>	<b>FORD 2.0 ECOBOOST / LAND ROVER</b>	<b>5304-150-5709</b>	<b>K03</b>
<b>TSM-BP-K1-4-13</b>	<b>FORD F150 GTDI DWD 3.5L</b>	<b>5303-970-0277</b>	<b>K0CG</b>
<b>TSM-BP-K1-5</b>	<b>VW VARIOS, 150 / 180 AUDI / SEAT</b>	<b>5304-151-5712</b>	<b>K03 K04</b>
<b>TSM-BP-K1-16</b>	<b>SPRINTER 2013 BITURBO 2G</b>	<b>1302-004-301 5304-150-5702 5304-970-0094</b>	<b>BV45 K04</b>
<b>TSM-BP-K1-17</b>	<b>VOLKSWAGEN CRAFTER / AMAROK</b>	<b>5304-1505706</b>	<b>K04-R2S K03 K04 BV45 BV50 K0CG</b>
<b>TSM-BP-K1-19</b>	<b>VARIOS MAZDA / VOLVO SEAT / AUDI / VW</b>	<b>5304-151-5733</b>	<b>K04</b>
<b>TSM-BP-K1-20</b>	<b>NISSAN NV350 2.5</b>	<b>5307-970-0268</b>	<b>K03</b>
<b>TSM-BP-K2-1</b>	<b>INDUSTRIAL, AGRICOLA Y MAS</b>		<b>K26 K27</b>



<b>TSM-BP-K2-8</b>	<b>M.B 906</b>	<b>5327-151-6810</b>	<b>K26 K27</b>
<b>TSM-BP-K2-9</b>	<b>MERCEDES BENZ 926</b>	<b>5327-970-7162</b>	<b>K26 K27</b>
<b>TSM-BP-K3-1 TSM-BP-K3-5</b>	<b>RANAULT KANGO PLANO</b>		<b>KP35</b>
<b>TSM-BP-K3-3</b>	<b>JETTA, EUROVAN PLANO</b>	<b>5443-152-3000</b>	<b>KP31 KP39 BV39 BV31</b>
<b>TSM-BP-K3-4</b>	<b>OVALADO EUROVAN</b>	<b>5443-152-3005</b>	<b>KP39 BV31 BV39</b>
<b>TSM-BP-K3-5B</b>	<b>SMART KANGOO</b>		<b>KP/BV31-39</b>
<b>TSM-BP-K3-6</b>	<b>LANCIA / PLANO</b>	<b>5435-150-3002 1000-970-0005</b>	<b>KP35</b>
<b>TSM-BP-K3-8</b>	<b>SPRINTER OVALADO CRAFTER KANGO</b>		<b>KP35 KP39</b>
<b>TSM-BP-K4-1</b>	<b>M.B 924</b>	<b>5326-151-5718</b>	<b>K24</b>
<b>TSM-BP-K5-1</b>	<b>M.B 904</b>	<b>5324-151-5714</b>	<b>K16</b>
<b>TSM-BP-K7-2</b>	<b>JOHN DEERE</b>	<b>5327-151-5700 RE505182 2266G/17.21D</b>	<b>K26 K27</b>

<b>TSM-BP-M1-1B</b>	<b>SUZUKI SWIFT / VW GOLF 1.4 Y MAS</b>		<b>TD02</b>
<b>TSM-BP-M2</b>	<b>VOLVO TWIN OVALADO</b>	<b>49131-06003</b>	<b>TD03 TD025</b>
<b>TSM-BP-M2-1</b>	<b>OPEL ASTRA / CORSA OVALADO</b>	<b>49131-06003</b>	<b>TD02</b>
<b>TSM-BP-M4-1B</b>	<b>STRATUS VOLVO OVALADO</b>	<b>49377-06050</b>	<b>TD04</b>
<b>TSM-BP-M6-1</b>	<b>CATERPILLAR 320 OVALADO</b>	<b>49178-22510</b>	<b>TD05 TD06</b>
<b>MELETT</b>	<b>SPRINTER BITURBO</b>	<b>1302-004-301</b>	<b>K04</b>
<b>TSM-BP-S2-1B</b>	<b>CATERPILLAR</b>	<b>167744</b>	<b>S200</b>
<b>TSM-BP-S3-1B</b>	<b>CATERPILLAR</b>	<b>199646 OR6829 167168</b>	<b>S3A S3B</b>
<b>TSM-BP-S4-1B</b>	<b>CATERPILLAR</b>	<b>167543</b>	<b>S300 S310 S300V110</b>
<b>TSM-BP-S6-1B</b>	<b>CATERPILLAR</b>	<b>316010</b>	<b>S400 S410T</b>
<b>TSM-BP-S8-1b</b>	<b>CATERPILLAR</b>	<b>51135 197651 5232-152-3001</b>	<b>S4D 4LE 4LF 3LD Y MAS</b>
<b>TSM-BP-S10-1B</b>	<b>JOHN DEERE / BOB CAT</b>	<b>315910</b>	<b>S100</b>

<b>TSM-BP-T3-2</b>	<b>TOYOTA HILUX 3.0</b>	<b>17201-30110</b>	<b>CT-VNT</b>
<b>TSM-BP-T8-1</b>	<b>TOYOTA HILUX INNOVA FORTUNER 2.8L</b>	<b>17201-11080</b>	<b>CT-VNT</b>
<b>TSM-BP-TSM-001</b>	<b>PLATO NUEVO DDEC 2 DDEC 3</b>		<b>TV45 / TV48 TMF5502</b>
<b>TSM-BP-TSM-T3</b>	<b>CON PIZARRA</b>		<b>T3</b>
<b>TSM-BP-TSM-T12</b>	<b>PLATO CATERPILLAR T12 / D8K-583K EXCAVADOR</b>	<b>407505-0014 6N7202 OR5908</b>	<b>T12</b>