



# CARTUCHOS CATÁLOGO 2021



/	CÓDIGO E&E / TSM	DATO TÉCNICO	NUMERO DE PARTE	MODELO
	TSM-B01-010	VW POLO 2013 AUDI A1 S1 SEAT 1.0 TSI PROPELA BILLET	1633-970-0002 04C145701C 04C145702J	B01G
	TSM-B03-000	BMW X6 X3 535i, 35i, 40i, 335i N55	1853-710-0500 1853-970-0000	B03
	TSM-B03-002	MERCEDES BENZ A CLASS 45 AMG	1855-710-0501 1855-970-0002 1855-970-0009 1855-970-0010 1855-970-0013	B03G
	TSM-B1-004	DEUTZ INDUSTRIAL ENGINE	1158-988-0008 1158-970-000	B1G
	TSM-B2-000	PERKINS TRACTOR BITURBO	2674A256 2674A266 2674A271 2674A237 1270-710-0001 1070-197-0002 1070-988-0002 1070-197-0003 1070-197-0005 1070-988-0005 1070-970-0002 1070-988-0012	B2

	<b>TSM-B2-002</b>	<b>PERKINS TRACTOR</b>	<b>2674A256 1270-710-0001 1070-197-0004</b>	<b>B2</b>
	<b>TSM-B2-004</b>	<b>FORD POWER STROKE BITURBO 6.4 L 2007 AL 2010</b>	<b>175416</b>	<b>B2V-V2S</b>
	<b>TSM-B2-007</b>	<b>GAS 2011</b>	<b>1270-710-0021</b>	<b>B2G</b>
	<b>TSM-B2-012</b>	<b>INTERNATIONAL MAXXFORCE 9 1326 DT466</b>	<b>1200-909-7002</b>	<b>B2UV</b>
<b>BITURBOS</b>	<b>TSM-B2-TSM- BT-CH</b>	<b>INTERNATIONAL MAXXFORCE 13</b>	<b>N/P 13870152303</b>	<b>B2NG</b>
<b>BITURBOS</b>	<b>TSM-B3-TSM- BT-G</b>	<b>INTERNATIONAL MAXXFORCE 13</b>	<b>NUM. CARACOL ESCAPE 13871016B60 N/P 13870152303</b>	<b>B3NS</b>

	<b>TSM-B3-000-C</b>	<b>APLICACIÓN EUROPEA</b>	<b>1853-710-0500</b>	<b>B3</b>
	<b>TSM-B3-001</b>	<b>FORD POWER STROKE BITURBO 6.4L F250 F350 F450 F550 V114 2008 AL 2010</b>	<b>177100</b>	<b>B3/V2S</b>
	<b>TSM-BM-000</b>	<b>VW AUDI SEAT A3 GOLF LEON 2.0 TDI PROPELA BILLET</b>	<b>04L253010K</b>	<b>BM70B</b>
	<b>TSM-BV40-000 K04-031</b>	<b>VW / SEAT ALTEA IBIZA / AUDI A1 /VW JETTA 2.0 TDI PROPELA BILLET</b>	<b>03L253009R</b>	<b>BV40</b>
	<b>TSM-BV40- TSM00</b>	<b>VW / PASSAT 2.0 TDI</b>	<b>03L253056E V500</b>	<b>BV40E-0005 DE ACTUADOR ELECTRONIC O Y GEOMETIA</b>
	<b>TSM-CO-002</b>	<b>MINI BMW 3 CIL. PROPELA BILLET GIRO REVERSO</b>	<b>7636784</b>	<b>GTDI12V</b>
	<b>TSM-CT-VNT3B</b>	<b>TOYOTA HILUX REVO 2.8L 1GD 2015</b>	<b>17201-11080</b>	<b>CT-VNT</b>
	<b>TSM-CT-VNT4</b>	<b>TOYOTA HILUX REVO 2.4L 2GD 2015</b>	<b>17201-11070</b>	<b>CT-VNT</b>

	<b>TSM-CZ-002</b>	<b>MMZ MINSK TRUCK BUS D245.</b>	<b>399-0314-174 399-0314-192</b>	<b>C14</b>
	<b>TSM-CZ-003</b>	<b>JOHN DEERE TRACTOR 4045H</b>	<b>RE531073 399-0323-115</b>	<b>K27-1156 K27-115</b>
	<b>TSM-GT12-008</b>	<b>SMART FORTWO 61HP 0.6LP</b>	<b>727211-0001</b>	<b>GT1238S</b>
	<b>TSM-GT14-006</b>	<b>AMAROK 2010 2.0 TDI CRAFTER 2011 TDI 2.0</b>	<b>8039655-5005 795090 803955</b>	<b>GTC1446V</b>
	<b>TSM-GT14-013</b>	<b>CHEVROLET CRUZE TRAX SONIC BUICK ENCORE 1.4</b>	<b>786825-0001</b>	<b>MGT1446MZG L</b>
	<b>TSM-GT14-015</b>	<b>DOGGE ABARTH 500 / FIAT 500 PUNTO / ALFA ROMEO GIULIETTA 16V 1.4</b>	<b>55238189</b>	<b>GT1446SZ</b>
	<b>TSM-GT14-016</b>	<b>ALFA ROMEO GIULIETTA JTDM</b>	<b>55233682 804963-0002</b>	<b>GT1446</b>
	<b>TSM-GT14-018</b>	<b>TRANSPORTER 2.0 TDI</b>	<b>03L253016</b>	<b>GTB1446VZ</b>
	<b>TSM-GT14- 029B</b>	<b>VW BEETLE JETTA, 1.8L TSI, GOLF 2.0 TFSI BILLET</b>	<b>817808-00011</b>	<b>MGT1446OZ</b>

	<b>TSM-GT14-044</b>	<b>FORD RANGER PUMA 2.2</b>	<b>831157-0002</b>	<b>GTD1449VZ</b>
	<b>TSM-GT14-049B</b>	<b>NISSAN JUKE 1.6 VERCION NUEVA</b>	<b>827388-003</b>	<b>MGT14462</b>
	<b>TSM-GT15-001</b>	<b>RENAULT TRAFIC 1.9 MEGANE LAGUNA</b>	<b>703245-0001</b>	<b>GT1549S</b>
	<b>TSM-GT15-011</b>	<b>SAAB 9.5, 9.3 150HP 2.0L</b>	<b>452204-0001</b>	<b>GT17525</b>
	<b>TSM-GT15-015</b>	<b>PEUGEOT / FIAT LANCIA SUSUKI</b>	<b>713667-0001</b>	<b>GT1549S</b>
	<b>TSM-GT15-019</b>	<b>VW GOLF, JETTA, BEETLE 1.9 GARRET</b>	<b>713672-5006S 433395-0007</b>	<b>GT1749V</b>
	<b>TSM-GT15-035</b>	<b>VW GOLF BORA / AUDI 1.9TDI / 2.0TDI</b>	<b>03G253016Q 703890-0034</b>	<b>GTA1749MV</b>
	<b>TSM-GT15-052</b>	<b>FORD MONDEO ESCORT 1.8 TD</b>	<b>452084-0004</b>	<b>GT1544</b>
	<b>TSM-GT15-076</b>	<b>SSANG YONG / ACTYON 2.0 XDI</b>	<b>A6640900880</b>	<b>GTB1549V</b>
	<b>TSM-GT15-094</b>	<b>BMW 114i 116i 118i 316i 320i N13B16M0</b>	<b>11627645759</b>	<b>MGT1549ZDL</b>

	<b>TSM-GT15-099</b>	<b>FORD EXPLORER TAURUS SHO LINCOLN ECOBOOST</b>	<b>790317-0002</b>	<b>MGT1549SL</b>
	<b>TSM-GT15-100</b>	<b>FORD EXPLORER TAURUS SHO LINCOLN ECOBOST V6</b>	<b>790317-0002</b>	<b>MGT1549SL</b>
	<b>TSM-GT16-000</b>	<b>EUROVAN, BORA GARRETT 1.9 TDI</b>	<b>751851-0003</b>	<b>GT1646V</b>
	<b>TSM-GT17-005</b>	<b>HYUNDAI H100 CARGA REDILAS</b>	<b>433352-0031</b>	<b>GT1749S</b>
	<b>TSM-GT17-042</b>	<b>PEUGEOT EXPERT FIAT 2.0 HDI</b>	<b>18031264</b>	<b>GT1749V</b>
	<b>TSM-GT17-060</b>	<b>FORD TRANSIT IZQUIERDO TRACCION TRASERA DE CARDAN 2.2</b>	<b>787556-0016</b>	<b>GTB1749V</b>
	<b>TSM-GT17-073</b>	<b>CITROEN JUMPER PEUGEOT FIAT DUCATO / PEUGEOT BOXER / 2.2</b>	<b>798128-0002</b>	<b>GTB1749VK</b>
	<b>TSM-GT17-074</b>	<b>FORD TRANSIT DERECHO TRACCION DELANTERA 2.2</b>	<b>786880-0006</b>	<b>GTB1749VK</b>
	<b>TSM-GT17-078</b>	<b>AUDI A6 TDI, A4, A5 2.7 TDI</b>	<b>769701-0003 7771159-0003 767805-0004</b>	<b>GTB1756VK</b>

	<b>TSM-GT17-101</b>	<b>JMC TRANSIT PROPELA BILLET</b>	<b>821962-0006</b>	<b>GT1752Z</b>
	<b>TSM-GT17-113</b>	<b>JETTA BEETLE 2.0 TSI REVERSE</b>	<b>19035830 06K145702A 814000-0013</b>	<b>MGT1752S</b>
	<b>TSM-GT18-004</b>	<b>M.B SPRINTER OM611</b>	<b>778794-0001</b>	<b>GT1852V</b>
	<b>TSM-GT18-014</b>	<b>URVAN 3.0 ZD30DD</b>	<b>771507-0001</b>	<b>GTA1852V GT23</b>
	<b>TSM-GT20-000</b>	<b>PERKINS CAT T4.40 CON VÁLVULA</b>	<b>451298-0045 451298-0024</b>	<b>GT2052S</b>
	<b>TSM-GT20-004</b>	<b>SAAB 9-3 2.0L</b>	<b>19024560 12755106 720168-0001</b>	<b>GT2052ELS</b>
	<b>TSM-GT20-008</b>	<b>PERKINS CAT 416 / 420 SIN VALVULA</b>	<b>451298-0023</b>	<b>GT2052S</b>
	<b>TSM-GT20-009</b>	<b>M.B FORD PERKINS SPRINTER 312 INDUSTRIAL MOTOR RANGER 4CIL 2.5L-D</b>	<b>451298-0010 451298-0022</b>	<b>GT2052S</b>
	<b>TSM-GT20-033</b>	<b>FORD TRANSIT LAND ROVER 2.4 TDCI</b>	<b>6C1Q6K68ZEE 752610-0009</b>	<b>GTA2052VK</b>
	<b>TSM-GT20-035</b>	<b>MERCEDES BENZ S- CLASS / C-CLASS C320 OM642 3.0L</b>		<b>GTA2056VK</b>

	<b>TSM-GT20-039</b>	<b>MERCEDES OM 642 3.0L</b>		<b>GTA2056VK</b>
	<b>TSM-GT20-045</b>	<b>PERKINS 3.3L</b>	<b>433289-0191 723190-0003 2674A405</b>	<b>GT2049S</b>
	<b>TSM-GT20-053</b>	<b>FIAT DUCATO / PEUGEOT MANGER 3.0 HDI</b>	<b>796122-0001 796122-0005</b>	<b>GTB2056LV</b>
	<b>TSM-GT20-062</b>	<b>M.B E350 / JEEP / M CLASS OM642</b>	<b>764809-0001 764809-0002</b>	<b>GTB2056VK</b>
	<b>TSM-GT20-070</b>	<b>FORD RANGER DURATORQ 3.2L TDCi</b>	<b>822182-0004 822182-0009</b>	<b>GTD2056VZK</b>
	<b>TSM-GT20-072</b>	<b>AUDI Q7 TDI GEN 2</b>	<b>839077-0002 839077-0008 839077-0009</b>	<b>GTD2060VZK</b>
	<b>TSM-GT22-001</b>	<b>SPRINTER OM 612 VALVULA MECANICA</b>	<b>A6120960339</b>	<b>GT2256Z</b>
	<b>TSM-GT22-002</b>	<b>M.B SPRINTER VAN OM647 2.7L ACTUADOR ELECTRONICO</b>	<b>703891-0137 736088-0001</b>	<b>GT2256VK</b>
	<b>TSM-GT22-020</b>	<b>BMW, X6 TWIN TURBO GIRO DERECHO</b>	<b>7590598A02</b>	<b>MGT2256S</b>
	<b>TSM-GT22-026</b>	<b>TOUAREG 3.0 TDI / AUDI A4 A6, A7, Q7 3.0TDI</b>	<b>776470</b>	<b>GTB2260VK</b>



	<b>TSM-GT22-031</b>	<b>HINO TRUCK EXCAVATOR 5.3L</b>	<b>17201E0630</b>	<b>GT22-59LS</b>
	<b>TSM-GT22-037</b>	<b>VW TOUAREG / AUDI Q7, A4, A5, A6 3.0 TDI</b>	<b>755729-0074</b>	<b>GTB2260VK</b>
	<b>TSM-GT22-042</b>	<b>HINO TRUCK DUTRO N04C S05C</b>	<b>773032-0047</b>	<b>GT2263KLNV</b>
	<b>TSM-GT22-043</b>	<b>BMW, X6, 50 IX, E71 TWIN TURBO N63B44 GIRO REVES S63</b>	<b>7589086</b>	<b>MGT2260SDJ</b>
	<b>TSM-GT22-049</b>	<b>PERKINS AGRICULTURA JCB</b>	<b>433289-0284</b>	<b>GT2556S</b>
	<b>TSM-GT22-052</b>	<b>HINO TRUCK TOYOTA COASTER 4.0L NO4C</b>	<b>783801-0024 17201-E7041</b>	<b>GT2263KLNV</b>
	<b>TSM-GT22- 058BR</b>	<b>FORD FOCUS R5 ECOBOOST GTDI BILLET</b>	<b>834142-0007</b>	<b>MGT2263DGLZ</b>
	<b>TSM-GT22-073</b>	<b>BMW X5 XDRIVE 50i / E70 / E71 / E72</b>	<b>768537-0034 810409-0006</b>	<b>MGT2256SL</b>
	<b>TSM-GT25-002</b>	<b>ISUZU ELF TRUCKS Y MAS 4HE1XS</b>	<b>431876-0109 8972098751</b>	<b>GT2560S RHF5</b>

	<b>TSM-GT25-005</b>	<b>PERKINS CAT 416 /420 PROPELA (VARIOS)</b>	<b>2674A225</b>	<b>GT2556S</b>
	<b>TSM-GT25-006</b>	<b>CAT-PERKINS TRACTOR T4.40 416 / 420 E</b>	<b>2674A209 433289-0185</b>	<b>GT2556S</b>
	<b>TSM-GT25-009</b>	<b>PERKINS INDUSTRIAL N14</b>	<b>433289-0220</b>	<b>GT2556S</b>
	<b>TSM-GT25-013</b>	<b>PERKINS AGRICULTURAL / JCB</b>	<b>433289-0299 762932-0001 762932-0002 762932-0005 762932-0006</b>	<b>GT2556S</b>
	<b>TSM-GT25-018</b>	<b>PERKINS VARIOS CONSTRUCCION INDUSTRIAL</b>	<b>433289-0426 2674A808</b>	<b>GT2560S</b>
	<b>TSM-GT25-019</b>	<b>PERKINS GEN SET 110A 4AT</b>	<b>433289-0255</b>	<b>GT2556S</b>
	<b>TSM-GT25-021</b>	<b>PERKINS VARIOS</b>	<b>10R9577 268997 478-4846</b>	<b>GT2556S</b>
	<b>TSM-GT25-024</b>	<b>MERCEDES BENZ OM904LA GARRET</b>	<b>729546-0001</b>	<b>GT2559S</b>
	<b>TSM-GT25-028</b>	<b>JCB VARIOS</b>	<b>773125-0005</b>	<b>GT2560S</b>

	<b>TSM-GT25-035</b>	<b>IVECO TRUCK 4.5D</b>	<b>819158-0002 819158-0004</b>	<b>GT2560NS</b>
	<b>CHRA-TSM-GT32-1</b>	<b>POWER STROKE 6.7 DE BALERO</b>	<b>US6193463 US6269642</b>	<b>GT32</b>
	<b>TSM-GT35-001</b>	<b>CAT PERKINS / AGRICULTURA / CONSTRUCCION 6.0L</b>	<b>709947-0008 2674A343</b>	<b>GT3571S</b>
	<b>TSM-GT35-006</b>	<b>PERKINS AGRICULTURAL TRACTOR</b>	<b>709947-0002</b>	<b>GT3571S</b>
	<b>GT37-TSM-CH</b>	<b>NAVISTAR NGD</b>		<b>GT37 GTA3782</b>
	<b>TSM-GT37-009</b>	<b>INTERNATIONAL NAVISTAR NGD</b>	<b>1825632c93 751363-0001</b>	<b>GT37 GTA3782</b>
	<b>TSM-GT37-019</b>	<b>NAVISTAR / INTERNATIONAL DT408P / DT466P</b>	<b>1836093C92 1826344C92 471097-0010</b>	<b>GTA3782</b>
	<b>TSM-GT40-015</b>	<b>DETROIT DIESEL TRUCK, BUS SERIES 50</b>	<b>715214-0001 23528044</b>	<b>GTA4088</b>
	<b>TSM-GT45-003</b>	<b>VOLVO TRUCK BUS D12B D380 D12C FM12</b>	<b>434251-0017</b>	<b>GT4594</b>

	<b>TSM-GT45-006</b>	<b>CATERPILLAR C13</b>	<b>712402-0038</b>	<b>GTA4502S</b>
	<b>TSM-GT45-013</b>	<b>VOLVO / BUS D12B / FM12</b>	<b>712402-0031 452164-0014</b>	<b>GT4594</b>
	<b>TSM-GTA-002-C1</b>	<b>DETROIT DIESEL TRUCK SERIE 60 DDEC5 PROPELA BILLET</b>	<b>720191-0086 758160-0006</b>	<b>GTA4502V</b>
	<b>TSM-GTA-006</b>	<b>DETROIT S-60 DDEC4 PROPELA GRANDE</b>	<b>712402-0008 R2352464</b>	<b>GTA4202</b>
	<b>TSM-GTA-018</b>	<b>DETROIT SERIE 60 DDEC 4 PROPELA CHICA</b>	<b>712402-0007 714788-0001</b>	<b>GTA4294</b>
	<b>TSM-GTP-000</b>	<b>FORD F250 F350 F SERIES / POWER STROKE / NAVISTAR V8 DIESEL 7.3</b>	<b>1825878C92 702650-0001</b>	<b>GTP38R</b>
	<b>TSM-GTP-001</b>	<b>FORD POWER 7.3L</b>	<b>1831434C96 702014-0017</b>	<b>GTP38R</b>
	<b>TSM-GTP-002</b>	<b>FORD NAVISTAR POWER STROKE 7.3 SUPERDUTY F SERIES</b>	<b>1831383C92 702012-0010</b>	<b>GTP38R</b>
	<b>TSM-GTP-004</b>	<b>FORD POWER 7.3L NAVISTAR NGD</b>	<b>449677-0003 1822869C91 170308</b>	<b>TP3801</b>

	<b>TSM-H1-001</b>	<b>CUMMINS 6BT / FORD</b>	<b>3523317 3545713</b>	<b>H1C</b>
	<b>TSM-H1-002</b>	<b>CUMMINS H1C PLATO CHICO 4BT</b>	<b>3523322</b>	<b>H1C</b>
	<b>TSM-H1-003</b>	<b>CUMMINS / I CASE INDUSTRIAL 6CT</b>	<b>3545701</b>	<b>H1E</b>
	<b>TSM-H1-005</b>	<b>6CTA CUMMINS SERIE C</b>	<b>3545698</b>	<b>H1E</b>
	<b>TSM-H1-006</b>	<b>6CTA CUMMINS SERIE C FREIGHTLINER</b>	<b>3545988</b>	<b>H1E</b>
	<b>TSM-H1-007</b>	<b>BUS / INDUSTRIAL / TRACTO 6CTA</b>	<b>354516</b>	<b>H1E WH1E</b>
	<b>TSM-H1-012</b>	<b>CUMMINS ELITE / H1C 6BTA / 6BTAA</b>	<b>3575060</b>	<b>H1C</b>
	<b>TSM-H1-018</b>	<b>CUMMINS MARINE 6BT / 6C / 6BT / 6BTA / 6BTAM</b>	<b>3526625 3545744 3534377 3538674</b>	<b>H1E</b>
	<b>TSM-H1-039</b>	<b>CUMMINS 6BTA</b>	<b>3532031 3575062 3536214 3534931</b>	<b>H1C WH1C</b>
	<b>TSM-H2-013</b>			
	<b>TSM-HTB-000</b>	<b>CUMMINS HT3B 350/400</b>	<b>3527046</b>	<b>HT3B</b>

	<b>TSM-HTB-008</b>	<b>CUMMINS N14 SELEC PLUS</b>	<b>3536804 3536805</b>	<b>HT60</b>
	<b>TSM-HE-000</b>	<b>RAM 5.9 3500 / 4000</b>	<b>4032347 4036835 4036836</b>	<b>HY35W HE351</b>
	<b>TSM-HE-008</b>	<b>FOTON TRUCK, CUMMINS</b>	<b>3773813</b>	<b>HE200WG</b>
	<b>HE-TSM-2WG</b>	<b>CATERPILLAR</b>	<b>5328733 D1908143047 DE006424</b>	<b>HE200WG</b>
	<b>TSM-HE-009</b>	<b>CUMMINS QSB / QSB4 / ISBE5 4.5 L</b>	<b>4043587</b>	<b>HE221W</b>
	<b>TSM-HE-010</b>	<b>CUMMINS GAZELLE</b>	<b>3768401</b>	<b>HE211W</b>
	<b>TSM-HT-002</b>	<b>NISSAN DATSUN RENAULT MASTER</b>	<b>047-230 047-00A 250-8271</b>	<b>HT12-19B</b>
	<b>TSM-HX-002</b>	<b>CUMMINS PEGASUS ISC QSC</b>	<b>4046058 4089927 4031321 3802769</b>	<b>HX40W</b>

	<b>TSM-HX-003</b>	<b>CUMMINS ISC</b>	<b>4031321</b>	<b>HX40W</b>
	<b>TSM-HX-005</b>	<b>CUMMINS ISB 6BTAA</b>	<b>3538421</b>	<b>HX35W</b>
	<b>TSM-HX-007</b>	<b>CUMMINS 4BT KOMATSU / INDUSTRIAL</b>	<b>3593410</b>	<b>HX30 HX30W</b>
	<b>TSM-HX-009</b>	<b>CUMMINS MARINO / EXCAVADOR / INDUSTRIAL 6BT</b>	<b>3537132</b>	<b>HX35</b>
	<b>TSM-HX-013</b>	<b>CUMMINS ISC</b>	<b>4089931 4039918</b>	<b>HX40W</b>
	<b>TSM-HX-021</b>	<b>CUMMINS / DODGE RAM / FORD</b>	<b>3537815</b>	<b>HX35W</b>
	<b>TSM-HX-029</b>	<b>CUMMINS / IVECO / INDUSTRIAL / AGRICULTURA</b>	<b>4027331 3767211 4042707 4042708 2840083</b>	<b>HX35W</b>

	<b>TSM-HX-032</b>	<b>CUMMINS / IVECO TRUCK PEGASUS</b>	<b>4027868</b>	<b>HX40W HE400FG</b>
	<b>TSM-HX-097</b>	<b>CUMMINS PEGASUS ISC / QSC BILLET</b>	<b>4027949 4038459 4089822</b>	<b>HX40W</b>
	<b>TSM-HX5-018- C</b>	<b>VOLVO D12 DODGE</b>	<b>4032332 3399965</b>	<b>HX52</b>
	<b>TSM-HX5-000</b>	<b>CUMMINS ISX1 /CUMMINS ISX2</b>	<b>4027807 4036892-B</b>	<b>HX55 HX55W</b>
	<b>TSM-HX5-002</b>	<b>CUMMINS ISM / M11 PLUS ELECTRONICO</b>	<b>3580726 2834419 2837414</b>	<b>HX55</b>
	<b>TSM-HX5-003</b>	<b>SCANIA DSC12</b>	<b>4027001 3591167 1485648</b>	<b>HX50W</b>
	<b>TSM-HX5-016</b>	<b>DOOSAN DV11</b>	<b>2836654</b>	<b>HX50W</b>



	<b>TSM-HX5-059</b>	<b>VOLVO TRUCK MD13</b>	<b>4031407 4043162 3790509</b>	<b>HX55</b>
	<b>TSM-HX25-001</b>	<b>CUMMINS / IVECO / INDUSTRIAL / EXCAVADORA KOMATSU 4 BTA</b>	<b>3539071 3599879 3599350</b>	<b>HX25 HX25W</b>
	<b>TSM-HX25-003</b>	<b>CUMMINS ISB / BUS / IVECO TRACTOR</b>	<b>3599027 4894978</b>	<b>HX27W</b>
	<b>TSM-HY3-002</b>	<b>CHRYSLER 2500 / 3500 / RAM.5.9L</b>	<b>4031485</b>	<b>HY35W</b>

	<b>TSM-HY3-009</b>	<b>CUMMINS TRUCK</b>	<b>4027812</b>	<b>HY35W</b>
	<b>TSM-K03-004-C</b>	<b>VW AUDI A4, A6 / SEAT / ALHAMBRA 1.8 150 HP SHARAN</b>	<b>5303-710-0511 5303-970-0025</b>	<b>K03</b>
	<b>TSM-K03-009</b>	<b>AUDI 2.7 L A6, S4 TWIN TURBO</b>	<b>5303-710-0509</b>	<b>K03</b>
	<b>TSM-K03-012</b>	<b>M.B A160 CDI M.B A170 CDI OM668DE17LA</b>	<b>5303-710-0512 5303-970-0060 6680960199 5303-970-0019</b>	<b>K03</b>
	<b>TSM-K03-014</b>	<b>PEUGEOT DUCATO</b>	<b>5303-970-0050</b>	<b>K03</b>
	<b>TSM-K03-016</b>	<b>VW GOLF BEETLE / AUDI SEAT 1.8 180 HP</b>	<b>5303-710-0516 5303-970-0052 5303-970-0053</b>	<b>K03</b>
	<b>TSM-K03-024</b>	<b>VW / BORA, GOLF GTI, GLI AUDI A4, A6, A3, A4 TT 2.0 TFSI</b>	<b>5303-710-0526 5303-970-0086 5303-970-0087 53039880105</b>	<b>K03</b>

	<b>TSM-K03-031</b>	<b>PEUGEOT 207 308 3008 1.6</b>	<b>5303-710-0533 5303-970-0104 5303-970-0120</b>	<b>K03</b>
	<b>TSM-K03-032</b>	<b>MINI COOPER / JOHN COOPER / WORK CHALLENGE</b>	<b>5307-710-0529 5303-970-0146 5303-970-0298</b>	<b>K03</b>
	<b>TSM-K03-036</b>	<b>BMW / MINI COOPER S / PEUGEOT 308 207 RC 1.6 175 HP</b>	<b>5303-710-0527</b>	<b>K03</b>
	<b>TSM-K03-039B</b>	<b>VW JETTA AUDI A3 2.0 TDI BILLET</b>	<b>5303-970-0132 5303-710-8005 5303-970-0137</b>	<b>K03 BV43</b>
	<b>TSM-K03-041</b>	<b>VM TIGUAN GOLF GT 1.4 TSI</b>	<b>5303-710-0524 5303-710-0537 5303-970-0099</b>	<b>K03</b>
	<b>TSM-K03-047 TSM-K03-072 TSM-K03-102</b>	<b>FORD MONDEO S- MAX GALAXY ECOBOOST 2.0 LAND ROVER</b>	<b>5303-710-0565 5303-970-0191 5303-970-0240 53039880287 53039880259</b>	<b>K03</b>
	<b>TSM-K03-051B</b>	<b>NISSAN NAVARA / PATHFINDER 2.5 dCi 2011-2012, NP300 FRONTIER BV45</b>	<b>5303-970-0262</b>	<b>BV45</b>

	<b>TSM-K03-052</b>	<b>IVECO INDUSTRIAL 2011 BILLET</b>	<b>5303970-0253 5303-970-0254 5303-970-0256</b>	<b>K03</b>
	<b>TSM-K03-055B</b>	<b>VW GOLF GT 2007 / 1.4 TSI 2015 PROPELA BILLET</b>	<b>03CI4570IR 5303-710-0564 5303-970-0249</b>	<b>K03</b>
	<b>TSM-K03-056</b>	<b>AUDI A4 TFSI 1.8 2G</b>	<b>06H145701K 5303-970-0119 5303-710-0536</b>	<b>K03</b>
	<b>TSM-K03-058B</b>	<b>NISSAN NAVARA PHATFINDER / URVAN 2.5 DCI PROPELA BILLET</b>	<b>14411-5X01A 5303-970-0210 5303-970-0337</b>	<b>K03 BV45</b>
	<b>TSM-K03-059</b>	<b>MB A200 MOTOR M26620LA</b>	<b>5303-710-0532 5303-970-7200 2660900080</b>	<b>K03</b>
	<b>TSM-K03-060</b>	<b>AUDI A3 TT PASSENGER CAR 1.8 TFSI</b>	<b>5303-970-0112 5303-710-0535 06J145702C</b>	<b>K03</b>
	<b>TSM-K03-061B</b>	<b>NISSAN URVAN NV- 350 / CARAVAN / ENFRIADO POR AGUA 2.5 DCI; BILLET</b>	<b>5303-970-0268 5303-970-0341 5303-970-0373 DT: 5303-970- 0719/ 14411-</b>	<b>BV45 BV40 K03</b>
	<b>TSM-K03-070</b>	<b>HYUNDAI H100 / GRAND STAREX 2.5 BILLET</b>	<b>5303-970-0226 28500-4A700 5303-988-0353</b>	<b>BV43</b>
	<b>TSM-K03-094</b>	<b>HYUNDAI GAMA 1.6T PROPELA BILLET</b>	<b>5303-970-0306 28500-28700</b>	<b>K03</b>
	<b>TSM-K04-007</b>	<b>CUPRA / AUDI S3 / TT 1.8</b>	<b>5304-710-0507 5304-970-0020 06A145704P</b>	<b>K04</b>

	<b>TSM-K04-013</b>	<b>VOLVO S40 V50 T5 / FORD FOCUS ST 2.5</b>	<b>5304-710-0513 5304-970-0033 5304-970-0130</b>	<b>K04</b>
	<b>TSM-K04-015</b>	<b>MAZDA CX9 / MAZDA SPEED 3 2.3</b>	<b>L3K913700E K0422-881 K0422-882 5304-710-9901</b>	<b>K04</b>
	<b>TSM-K04-017</b>	<b>AUDI A8 / AUDI Q7 / VW TOUAREG V6 3.0 TDI 223HP</b>	<b>059145702F 5304-970-0054 5303-710-0530 5304-970-0035</b>	<b>BV50</b>
	<b>TSM-K04-019</b>	<b>MAZDA CX7 DISI NA 2.3</b>	<b>5304-710-9904 5304-710-9907 L33E13700B</b>	<b>K0422-582 K0422-583 K04</b>
<b>BITURBOS</b>	<b>TSM-K04-020</b>	<b>M.B SPRINTER BITURBO 1 G OM646</b>	<b>5304-710-0519 6460900380 5304-970-0057</b>	<b>K04</b>
<b>BITURBOS</b>	<b>TSM-KP39-009</b>	<b>M.B SPRINTER BITURBO OM646 1G</b>	<b>5439-710-0504 6460900280 5439-970-0033</b>	<b>KP39</b>
	<b>TSM-K04-021</b>	<b>OPEL / ASTRA G 2.0 16V</b>	<b>5304-710-0515 5304-970-0048</b>	<b>K04</b>
	<b>TSM-K04-023- C</b>	<b>AUDI S3 / CUPRA 2.0 TFSI</b>	<b>5304-710-0518 5304-970-0064 06F145702C</b>	<b>K04</b>
	<b>TSM-K04-027</b>	<b>SAAB 9-3 / SAAB 9-5 / PONTIAC / OPEL / VERANO 2.0</b>	<b>5304-710-0517</b>	<b>K04</b>
	<b>TSM-K04-034B</b>	<b>DEUTZ 7 / INDUSTRIAL / TRACTOR</b>	<b>5304-710-0520 5304-970-0075 5304-970-0089</b>	<b>K04</b>
	<b>TSM-K04-035</b>	<b>ALFA ROMEO GIULIETTA 1.8 TBI</b>	<b>5304-970-0090 55224276</b>	<b>K04</b>

<b>BITURBOS</b>	<b>TSM-K0CG-000</b>	<b>FORD F150 BITURBO BILLET 3.2 GTDI REVERSE (GIRO IZQUIERDO)</b>	<b>179205 BL3E9G438VA</b>	<b>K0CG</b>
<b>BITURBOS</b>	<b>TSM-K0CG-001</b>	<b>FORD F150 BITURBO BILLET 3.2 GTDI REVERSE (GIRO DERECHO)</b>	<b>179204</b>	<b>K0CG</b>
	<b>TSM-K0CG- 002B</b>	<b>FORD F150 / GTDI DWD 3.5L / FORD LOBO (GIRO DERECHO)</b>	<b>5303-970-0276 5303-970-0469 DL3E 6K682 AE 15114 110927 GHYFA</b>	<b>K0CG</b>
	<b>TSM-K0CG- 003B</b>	<b>FORD F150 GTDI DWD 3.5L / FORD LOBO 2015 (LADO DERECHO LADO DEL CONDUCTOR) (GIRO IZQUIERDO)</b>	<b>5303-970-0277 5303-970-0470 DL3E 6C879 AE 15115 220832 GHYFA</b>	<b>K0CG</b>
	<b>TSM-K16-000</b>	<b>M.B OM904 BUS PASAJERO</b>	<b>5316-710-0016 5316-970-7129 9040967499</b>	<b>K16</b>
	<b>TSM-K16-000- C</b>	<b>M.B OM904 BUS PASAJERO</b>	<b>5316-710-0016 5316-970-7129 9040967499</b>	<b>K16</b>

	<b>TSM-K24-000</b>	<b>MB OM 924 BUS OM924LA DE PASAJEROS</b>	<b>5324-970-7113 5324-970-7111 A9240961599</b>	<b>K24</b>
	<b>TSM-K24-000- C</b>	<b>MB OM 924 BUS OM924LA DE PASAJEROS</b>	<b>5324-970-7113 5324-970-7111 A9240961599</b>	<b>K24</b>
	<b>K24-EGR-TSM</b>	<b>MB EGR OM 924 FLECHA CHICA DE PASAJEROS</b>		<b>K24</b>
	<b>TSM-K24- MWM</b>	<b>MWM INTERNATIONAL MAXX FORCE 6 CIL</b>		<b>K24</b>
	<b>TSM-K27-002</b>	<b>M.B OM906 / TRUCK / BUS</b>	<b>5327-710-0159 5327-970-7100 5327-970-7104</b>	<b>K27</b>
	<b>TSM-K27-005- C1</b>	<b>MERCEDES BENZ OM926LA</b>	<b>5327-970-7208 9260964399</b>	<b>K27</b>
	<b>TSM-K29-000</b>	<b>MAN TRUCK D2066LF</b>	<b>5329-710-0030</b>	<b>K29</b>

	<b>TSM-KP31-000</b>	<b>SMART FORTWO 1999-2011 OM66DE08LA</b>	<b>6600900980 5431-710-0500 5431-970-0000</b>	<b>KP31</b>
	<b>TSM-KP35-001</b>	<b>RENAULT KANGOO 1.5</b>	<b>5435-710-0500 5435-970-0000 820000351439</b>	<b>KP35</b>
	<b>TSM-KP39-001- C</b>	<b>VW EUROVAN 1.9 TDI</b>	<b>5439-970-0022 038253014G</b>	<b>KP39 BV39</b>
	<b>TSM-KP39-003</b>	<b>VW JETTA 1.9 TDI</b>	<b>5339-970-0009 038253016L 038253019J</b>	<b>KP39</b>
	<b>TSM-KP39-006</b>	<b>VW TRANSPORTER TDI (T5) 1.9 TDI</b>	<b>5439-710-8008 5439-970-0057 03G253016F</b>	<b>KP39 BV39</b>
	<b>TSM-KP39-007</b>	<b>VW BORA / AUDI A3 1.9 TDI</b>	<b>5439-710-8004 5339 970 0029 03G253019K</b>	<b>KP39</b>
	<b>TSM-KP39- 019B</b>	<b>VENTO AUDI A1 / VW POLO PASSAT / SEAT 1.6 TDI PROPELA BILLET</b>	<b>5439-710-0531 5439-970-0086 03L253016A</b>	<b>BV39</b>
	<b>TSM-KP39-021</b>	<b>FORD FOCUS / FIESTA VOLVO 1.6 ECOBOOST</b>	<b>5439-970-0124 CJ5G6K682BA</b>	<b>KP39</b>
	<b>TSM-KP39-026- C</b>	<b>VW GOLF BORA 1.9 TDI</b>	<b>5439-970-0081</b>	<b>BV39</b>
<b>BITURBOS</b>	<b>TSM-R2S-000- H</b>	<b>VW AMAROK 2.0 BILLET</b>	<b>03L145715A 1000-970-0026</b>	<b>KP35-R2S</b>



<b>BITURBOS</b>	<b>TSM-R2S-000-L</b>	<b>VW AMAROK 2.0 BILLET</b>	<b>03L145715A 1000-970-0026</b>	<b>K04-R2S</b>
	<b>TSM-R2S-000-L1</b>	<b>VW AMAROK 2.0 2011 BILLET</b>	<b>5304-710-0551 1000-970-0027 03L145715A</b>	<b>K04-R2S</b>
<b>BITURBOS</b>	<b>TSM-R2S-001-LB</b>	<b>SPRINTER BIT 2G BILLET GRANDE</b>	<b>1000-970-0074 5304-710-0545 6510906380</b>	<b>K04-R2S</b>
<b>BITURBOS</b>	<b>TSM-R2S-003-HB</b>	<b>SPRINTER BIT 2G BILLET PEQUEÑO</b>	<b>5439-710-0524</b>	<b>KP39-R2S</b>
<b>BITURBOS</b>	<b>TSM-R2S-002-H</b>	<b>INTERNATIONAL TRUCK MAXXFORCE 5 V126 VT275 / CF500-TF600 BITURBO (PEQUEÑO)</b>	<b>5316-710-0537 80000174669</b>	<b>K16-R2S</b>
<b>BITURBOS</b>	<b>TSM-R2S-002-L</b>	<b>INTERNATIONAL TRUCK MAXXFORCE 5 V126 / VT275 / CF500-TF600 BITURBO (GRANDE)</b>	<b>5327-710-0199 80000174078</b>	<b>K27-R2S</b>
<b>BITURBOS</b>	<b>TSM-R2S-005-HB</b>	<b>VW CRAFTER BITURBO 2.0 TDI 2010 BILLET</b>	<b>1000-970-0030 03L145715B 03L145873D</b>	<b>KP35-R2S</b>
<b>BITURBOS</b>	<b>TSM-R2S-005-LB</b>	<b>VW CRAFTER BITURBO 2.0 TDI 2010 BILLET</b>	<b>1000-970-0030 03L145715B</b>	<b>K04-R2S</b>
	<b>TSM-R2S-009-L</b>	<b>VW AMAROK 2.0 2011</b>	<b>03L14570IS 1000-970-0051 5304-710-0553</b>	<b>K04-R2S</b>
<b>BITURBOS</b>	<b>TSM-R2S-010-HB</b>	<b>VW MAN BITURBO ( PEQUEÑO ) BILLET</b>	<b>1000-970-0105 51.09101-7223</b>	<b>B1UG-R2S</b>
<b>BITURBOS</b>	<b>TSM-R2S-010-L</b>	<b>VW MAN BITURBO ( GRANDE ) BILLET</b>	<b>1000-970-0105 MAN</b>	<b>B2US-R2S</b>

<b>BITURBOS</b>	<b>TSM-R2S-018-H</b>	<b>MAN TRUCK D0836LFL51 BITURBO (PEQUEÑO)</b>	<b>5324-710-0026 1000-970-0003 5324-970-7124</b>	<b>K24-R2S</b>
<b>BITURBOS</b>	<b>TSM-R2S-018-L</b>	<b>MAN TRUCK D0836LFL51 BITURBO (GRANDE)</b>	<b>5327-710-0197 1000-970-0003 5327-970-6908</b>	<b>K27-R2S</b>
<b>BITURBOS</b>	<b>TSM-R2S-020-H</b>	<b>MAN TRUCK D0834LFL51 BITURBO (PEQUEÑO)</b>	<b>1000-970-0049 1250-710-0000 5316-970-0029</b>	<b>K16-R2S</b>
<b>BITURBOS</b>	<b>TSM-R2S-020-L</b>	<b>MAN TRUCK D0834LFL51 BITURBO (GRANDE)</b>	<b>1000-970-0049 5326-710-0085 5326-970-0007</b>	<b>K26-R2S</b>
<b>BITURBOS</b>	<b>TSM-R2S-021-H</b>	<b>BMW X1 23dX BITURBO (PEQUEÑO)</b>	<b>1000-970-0006 5435-710-0508 5435-970-0036</b>	<b>KP35-R2S</b>
<b>BITURBOS</b>	<b>TSM-R2S-021-L</b>	<b>BMW X1 23dX BITURBO (GRANDE)</b>	<b>1000-970-0006 1000-970-0014 5316-970-0020</b>	<b>K16-R2S</b>
<b>BITURBOS</b>	<b>TSM-R2S-026-H</b>	<b>MAN TRUCK D0836 BITURBO (PEQUEÑO)</b>	<b>1000-970-0107</b>	<b>B1US-R2S</b>
<b>BITURBOS</b>	<b>TSM-R2S-026-L</b>	<b>MAN TRUCK D0836 BITURBO (GRANDE)</b>	<b>1000-970-0107</b>	<b>B2US-R2S</b>
	<b>TSM-RH6-003</b>	<b>GM3 GM4 CHEVROLET PICKUP 6.5L</b>	<b>171076 12521577</b>	<b>RHC6</b>
	<b>TSM-RH6-007</b>	<b>YANMAR MARINO</b>	<b>VA220033 19773-18011 MYBH</b>	<b>RHE62 RHE62W</b>
	<b>TSM-RHB5-012</b>	<b>FIAT PUNTO GT VL7</b>	<b>VA810042 VA180047</b>	<b>RHB52</b>

	<b>TSM-RHF3-002</b>	<b>FIAT ALFA ROMEO LACIA PUNTO BRAVO / ABARTH / VL36/VL38 1.4</b>	<b>55212916 55222014</b>	<b>RHF3</b>
	<b>TSM-RHF3-003</b>	<b>CK27 / CK30 / KUBOTA / TRACTOR / EXCAVATOR</b>	<b>1G924-17011 4G924-17011 VD410096</b>	<b>RHF3</b>
	<b>TSM-RHF3-004</b>	<b>KUBOTA</b>	<b>VA410152</b>	<b>RHF3</b>
	<b>TSM-RHF3-005</b>	<b>KUBOTA PC56-7 / BOBCAT TRACTOR</b>	<b>VA410152 1G491-17010 1G491-17011 1G491-17012</b>	<b>RHF3</b>
	<b>TSM-RHF3-012</b>	<b>VW TOURAN / AUDI A3 1.2TSI BILLET</b>	<b>03F145701F 03F145701L</b>	<b>JHJ RHF3</b>
	<b>TSM-RHF3-024</b>	<b>ALFA ROMEO / FIAT PUNTO LINEA 1.4 TB 16V</b>	<b>19017066</b>	<b>RHF3</b>
	<b>TSM-RHF3- 033B</b>	<b>MB A-CLASS BILLET</b>	<b>AL-0067 A2700902280</b>	<b>RHF3 JHJ</b>
	<b>TSM-RHF3- 035BR</b>	<b>VW JETTA PASSAT / SEAT / AUDI 1.4TSI BILLET REVERSE</b>	<b>04E145721F 10685-08</b>	<b>JHJ</b>
	<b>TSM-RHF3-040</b>	<b>KUBOTA CONSTRUCTION EXCAVATOR</b>	<b>CK26</b>	<b>RHF3</b>
	<b>TSM-RHF3-041</b>	<b>CK41 KUBOTA EXCAVADOR TRACTOR LOADER 1.9L</b>	<b>LJ700-17010 VB410140 1J700-17012</b>	<b>RHF3</b>
	<b>TSM-RHF3- 042B</b>	<b>VW GOLF AUDI A1/A3 1.2L BILLET</b>	<b>03F145701T 03F145701S</b>	<b>JHJ</b>

	<b>TSM-RHF3-044</b>	<b>VW SEAT 1.4 TSI / TFSI</b>	<b>04E 145 721 B 04E 145 704 C 04E 145 704 P</b>	<b>JHJ</b>
	<b>TSM-RHF3- 053B</b>	<b>VW POLO TOURAN / AUDI A1 / SEAT 1.2 TSI / CADDY</b>	<b>03F145701H</b>	<b>JHJ</b>
	<b>TSM-RHF3- 055B</b>	<b>M.B C CLASS 180 BILLET</b>	<b>AL-0070 A2740902180</b>	<b>JHJ</b>
	<b>TSM-RHF4-000</b>	<b>SHIBAUARA NEW HOLLAND / AGRICULTURAL</b>	<b>S12 AS12</b>	<b>RHF4</b>
	<b>TSM-RHF4-003</b>	<b>SPRINTER VITO VIANO 2.2 DE UN TURBO</b>	<b>A6460960199 VV14</b>	<b>RHF4V</b>
	<b>TSM-RHF4-016</b>	<b>MITSUBISHI L200 / W200 VT10</b>	<b>1515A029</b>	<b>RHF4</b>
	<b>TSM-RHF4-017</b>	<b>MB VITO 111/ W639 CDI OM646</b>	<b>A6460901380 VF40A03171</b>	<b>VV19 RHF4V</b>
	<b>TSM-RHF4-018</b>	<b>NISSAN NAVARA FRONTIER 2.5 /SOLO ACEITE</b>	<b>14411-VK500 VN3</b>	<b>RHF4</b>
	<b>TSM-RHF4-028</b>	<b>MB E-CLASS W212</b>	<b>A2710903480 AL-0065 110921-0252</b>	<b>JHJ RHF4</b>
	<b>TSM-RHF4-038</b>	<b>NISSAN NP300 CABSTAR ENFRIADO POR AGUA</b>	<b>14411-MB40B VN4</b>	<b>RHF4H</b>

	<b>TSM-RHF4-040</b>	<b>SUBARU OUTBACK 2.0D</b>	<b>VF50 / VF55</b>	<b>RHF4V</b>
	<b>TSM-RHF4-042</b>	<b>SHIHAURA AGRICULTURAL ENGINES N844L</b>	<b>NZ870564 AS11 VA420057 135756170</b>	<b>RHF4</b>
	<b>TSM-RHF4-049</b>	<b>M.B B-CLASS 2.0 PROPELA BILLET</b>	<b>A2740903580 160216-0178 160216-0126</b>	<b>JHJ</b>
	<b>TSM-RHF4- 051B</b>	<b>M.B C-CLASS / E-CLASS 2.0 PROPELA BILLET</b>	<b>AL-0071 AL-0072 150318-0374 150318-0324</b>	<b>JHJ</b>
	<b>TSM-RHF4-053</b>	<b>TOYOTA HILUX VIGO VB31</b>	<b>17201-0L070</b>	<b>RHV4</b>
	<b>TSM-RHF4- 059BR</b>	<b>AUDI A3 / SEAT LEON / SKODA OCTAVIA 1.8 TFSI PROPELA BILLET REVERSE</b>	<b>06K145701S 06K145701E 06K145701M</b>	<b>RHF4 JHJ</b>
	<b>TSM-RHF4- 072B</b>	<b>M.B A-CLASS 250 W176 CLA-CLASS PROPELA BILLET</b>	<b>AL-0069 120725-0252 A2700901880</b>	<b>JHJ</b>
	<b>TSM-RHF4-081</b>	<b>M.B C-CLASS E- CLASS W207</b>	<b>AL-0066 A2710903580</b>	<b>JHJ</b>
	<b>TSM-RHF5-001</b>	<b>SUBARU LEGACY VF38/VF40</b>	<b>14411AA470 VA430072</b>	<b>RHF5H</b>
	<b>TSM-RHF5-002</b>	<b>SUBARU IMPREZA 2.0 L / 2.5 L</b>	<b>VF39 N/P 14411AA572</b>	<b>RHF55</b>
	<b>TSM-RHF5-007</b>	<b>CYEG / YANMAR / MOTOR INDUSTRIAL / MARINO</b>	<b>VD430095 129935-18010</b>	<b>RHF5</b>

	<b>TSM-RHF5-009</b>	<b>ISUZU NRR / GMC / 5.2L</b>	<b>897336-1811 VAX55004</b>	<b>RHF5</b>
	<b>TSM-RHF5-024</b>	<b>ISUZU INDUSTRIAL / TRUCK</b>	<b>VA440031</b>	<b>RHF55</b>
	<b>TSM-RHF5-024- 1</b>	<b>ISUZU NPR75 / NQR75 / INDUSTRIAL FAN MOTOR</b>	<b>CIES CIFK</b>	<b>RHF55</b>
	<b>TSM-RHF5-026</b>	<b>AUDI A4 A5 A6 S4 S5 Q5 T 2.0</b>	<b>06H145702L</b>	<b>JH5</b>
	<b>TSM-RHF5-027</b>	<b>VW PASSAT CC TIGUAN; JETTA AUDI Q5 2.0TSI</b>	<b>06J145703N 06J145574D 06J145713F</b>	<b>RHF5 JH5</b>
	<b>TSM-RHF5- 031BR</b>	<b>AUDI A4, A5, A6 2.0L</b>	<b>06L145702M 06L145702P IS20</b>	<b>RHF5 JH5</b>
	<b>TSM-RHF5-033</b>	<b>AUDI TT S3 2.0TSI VW MK7, IS38 PROPELA BILLET</b>	<b>06K145722H 06K145722T 06K145702N</b>	<b>JHJ</b>
	<b>TSM-RHF5-045 TSM-RHF5-078*</b>	<b>ISUZU NKR 3.0 TDI</b>	<b>VAA30023 8973815070 VIF</b>	<b>RHF5V</b>

	<b>TSM-RHF5-051</b>	<b>AUDI 4.0 TFSI TWIN TURBO</b>	<b>079145703A 079145703B 079145703F</b>	<b>JH5 IT</b>
	<b>TSM- RHF5- 055</b>	<b>AUDI RS6 4.0, A6, A7 S7, A8, S8 4.0 TFSI</b>	<b>079145704A 079145704B 079145704E</b>	<b>JHJ</b>
	<b>TSM-RHF5-065</b>	<b>ISUZU TRUCK NEW 4J</b>	<b>VIFR VB430132 VIFV 8980540110</b>	<b>RHF5</b>
	<b>RHF5-089B</b>	<b>AUDI RS6 2016 / AUDI A6, A7, A8, S8 4.0L TFSI V8 TWIN TURBO</b>	<b>079145704K 079145722B</b>	<b>JHJ</b>
	<b>TSM-S1-000</b>	<b>JHON DEERE BOB CAT DEUTZ / VALMET / STEYR / VALTRA / MOTOR INDUSTRIAL /</b>	<b>18115782 314995 04178664KZ</b>	<b>S1B</b>
	<b>TSM-S1-002</b>	<b>DEUTZ INDUST/ NEW HOLLAND</b>	<b>318280 04258205KZ</b>	<b>S100</b>
	<b>TSM-S1-006</b>	<b>DEUTZ / GREAVES / TRACTOR / GENERADOR / INDUSTRIAL</b>	<b>318282 318281 318167</b>	<b>S100</b>
	<b>TSM-S1-007</b>	<b>JONH DEERE VARIOS</b>	<b>RE521157 RE518228 176348</b>	<b>S1B032</b>
	<b>TSM-S1-009</b>	<b>JOHN DEERE</b>	<b>RE554959 1153-970-0049</b>	<b>S1BG036</b>

	<b>TSM-S1-010</b>	<b>VALTRA</b>	<b>1153-970-0007 88647600</b>	<b>S1BS006</b>
	<b>TSM-S1-013</b>	<b>JOHN DEERE TRACTOR</b>	<b>316101 RE71550</b>	<b>S1B</b>
	<b>TSM-S1-014</b>	<b>DEUTZ</b>	<b>317048</b>	<b>S100</b>
	<b>TSM-S2-003</b>	<b>CAT 3126B / 950 8.962 LOADER</b>	<b>178190 185-8016</b>	<b>S200AG</b>
	<b>TSM-S2-004</b>	<b>DEUTZ / TRUCKS / MOTOR INDUSTRIAL Y MAS</b>	<b>5620-710-0001</b>	<b>S200G</b>
	<b>TSM-S2-010</b>	<b>DEUTZ / TRUCKS / MOTOR INDUSTRIAL Y MAS (CARTUCHO PEQUEÑO)</b>	<b>318807 318519 1272-970-0000</b>	<b>S200G</b>
	<b>TSM-S2-036</b>	<b>DEUTZ / MOTOR INDUSTRIAL VOLVO / MOTOR INDUSTRIAL PENTA</b>	<b>318443 04258659KZ</b>	<b>S200</b>
	<b>TSM-S2-058</b>	<b>JOHN DEERE / GENERADOR</b>	<b>318613 318569 174735 RE508973</b>	<b>S2A</b>
	<b>TSM-S2-071</b>	<b>CAT 3116 / EXCAVADOR</b>	<b>166773 0R6743 318409</b>	<b>S2EGL094</b>



	<b>TSM-S2-083</b>	<b>JOHN DEERE 6068H</b>	<b>176638 177259 177261 477259 314523</b>	<b>S200</b>
	<b>TSM-S2-105</b>	<b>CATERPILLAR 3116</b>	<b>314522 167420 100-5865 166321</b>	<b>S2E S2ES083</b>
	<b>TSM-S2-111</b>	<b>CATERPILLAR TRUCK C7</b>	<b>178187 171754</b>	<b>S200G</b>
	<b>TSM-S2-115</b>	<b>CATERPILLAR EXCAVATOR 325C, MILITARY</b>	<b>178387</b>	<b>S200A</b>
	<b>TSM-S2-122</b>	<b>CATERPILLAS TRUCK 3126B</b>	<b>178186 171746 195-5994</b>	<b>S200</b>
	<b>TSM-S3-001</b>	<b>CATERPILLAR 3126B</b>	<b>171999 OR7569 178468 171576</b>	<b>S300G</b>
	<b>TSM-S3-002</b>	<b>CATERPILLAR C9 972 LOADER</b>	<b>178189</b>	<b>S310G080</b>
	<b>TSM-S3-006</b>	<b>CAT / 175278 / PERKINS / GENERADOR SET 50 HZ Y MAS</b>	<b>530105</b>	<b>S310</b>
	<b>TSM-S3-017-C</b>	<b>INTERNATIONAL DT465/570 MAXXFORCE 1313 PROPELA BILLET</b>	<b>173900 1842337C94</b>	<b>S300V110</b>
	<b>TSM-S3-022</b>	<b>INTERNATIONAL MAXXFORCE TRUCK DT 466 1313</b>	<b>179035 178587</b>	<b>S300V129</b>

	<b>TSM-S3-024</b>	<b>INTERNATIONAL TRUCK / BUS / MAXXFORCE DT466 1313</b>	<b>178556 173941 173942 5010313R94 1842218C92</b>	<b>S300V111</b>
	<b>TSM-S3-026</b>	<b>CATERPILLAR 3306</b>	<b>170232</b>	<b>S3BSL115</b>
	<b>TSM-S3-070</b>	<b>CATERPILLAR C10</b>	<b>178196 172315 172345 173413 204-6489</b>	<b>S310</b>
	<b>TSM-T2-000</b>	<b>LAND ROVER DISCOVER Y MAS</b>	<b>443854-0110 452055-0004</b>	<b>T250-04</b>
	<b>TSM-T2-002</b>	<b>MITSUBISHI ECLIPSE 94-97 2.0L</b>	<b>431876-0059 466491-0003</b>	<b>TB2566</b>
	<b>TSM-T2-008</b>	<b>FORD NEW HOLLAND/ T250-01</b>	<b>87800959 465153-0003 443850-0065 87800959</b>	<b>T-250</b>

	<b>TSM-T2-018</b>	<b>PERKINS PHAISER</b>	<b>2674A150 443854-0106</b>	<b>TB2558</b>
	<b>TSM-T2-021</b>	<b>IZUZU PIZZARRA NKR</b>	<b>466409-0001 8971056180</b>	<b>TB2568</b>
	<b>TSM-T2-032</b>	<b>FIAT PUNTO 1.7 FIAT STRADA PUNTO</b>	<b>466856-0003 464224102</b>	<b>TBO227</b>
	<b>TSM-T2-041</b>	<b>NISSAN 300ZX V6 TWIN TURBO (IZQUIERDO DERECHO)</b>	<b>431876-0070</b>	<b>TB2207</b>
	<b>TSM-T2-050-C</b>	<b>ISUZU TRUCK / BUS</b>	<b>430425-0055 CARBON SEAL</b>	<b>TB2518</b>
	<b>TSM-T2-061</b>	<b>IVECO SOFIM</b>	<b>443854-0098 466974-0005</b>	<b>TB2534</b>
	<b>TSM-T2-074</b>	<b>PERKINS TRACTOR / MASSEY FERGUSON</b>	<b>2674A055 079513 711858-0001 452058-0002 443854-0129</b>	<b>TB2556</b>
	<b>TSM-T3-002</b>	<b>PERKINS / INDUSTRIAL / DEUTZ / 1CB</b>	<b>2674399 466674-0001 409172-0045</b>	<b>TA3107 TA3123 TA3112</b>
	<b>TSM-T3-002-1</b>	<b>PERKINS / M.B TRUCK, INDUSTRIAL / AGRICULTURAL / NAVISTAR / M.B 900</b>	<b>2674390 465776-0003</b>	<b>TA3106 TA3107 TA3114</b>

	<b>TSM-T3-003</b>	<b>JOHN DEERE / TRACTOR AGRICULTURA</b>	<b>409172-0054- RE32203</b>	<b>TA3401</b>
	<b>TSM-T3-004</b>	<b>JOHN DEERE INDUSTRIAL</b>	<b>409172-0038 RE26391</b>	<b>TA3404 TA3401</b>
	<b>TSM-T3-005</b>	<b>JOHN DEERE / SARAN TRACTOR SERIES 300 MOTOR 4239T / 4276T / GEN SET</b>	<b>RE40414 465593-0008</b>	<b>TA3404</b>
	<b>TSM-T3-009</b>	<b>EXCAVADOR / KOMATSU</b>	<b>465636-0206</b>	<b>TA3103</b>
	<b>TSM-T3-017</b>	<b>PERKINS MASSEY FERGUSON</b>	<b>2674A104 466778-0002 466778-0008</b>	<b>TA0315</b>
	<b>TSM-T3-021</b>	<b>CHRYSLER LEBARON, NEW YORKER SHELBY</b>	<b>466298-0001 465733-0002 4105798</b>	<b>TB0335</b>
	<b>TSM-T3-026</b>	<b>PEUGEOT 505 / LAND ROVER SANTANA</b>	<b>465318-003</b>	<b>TA0302</b>
	<b>TSM-T3-040</b>	<b>FORD / NEW HOLLAND TRACTOR 7710</b>	<b>465438-0005 409172-0062 466746-0003</b>	<b>TA3119</b>

	<b>TSM-T3-042</b>	<b>JOHN DEERE-INDUST 6068T</b>	<b>RE44801</b>	<b>TA3801 TA3802 TA3803</b>
	<b>TSM-T3-046</b>	<b>PERKINS</b>	<b>409172-0094 2674A147 466674-0003</b>	<b>TA3123</b>
	<b>TSM-T3-048</b>	<b>JOHN DEERE 6068T</b>	<b>471050-0005 RE503635</b>	<b>T350-04</b>
	<b>TSM-T3-058</b>	<b>PERKINS INDUSTRIAL RUSTON &amp; HORNSBY</b>	<b>2674A076 466346-0001</b>	<b>TA3123</b>
	<b>TSM-T3-067</b>	<b>PERKINS DIVERSE</b>	<b>409172-0052 2674A394</b>	<b>TA3120</b>
	<b>TSM-T3-068</b>	<b>JOHN DEERE TRACTOR 4093T</b>	<b>446311-0002</b>	<b>T300-02</b>
	<b>TSM-T3-069</b>	<b>JOHN DEERE TRACTOR 350</b>	<b>RE59379 471049-0003 446311-0006</b>	<b>T300-08</b>
	<b>TSM-T4-002</b>	<b>CATERPILLAR 3304 / EXCAVATOR EARTH MOVING / VOLVO F86, B57, A65</b>	<b>4N6860 465592-0001</b>	<b>T04B91</b>
	<b>TSM-T4-010</b>	<b>NAVISTAR DT466 / DT573 / DVT573</b>	<b>684698C91 409770-0006</b>	<b>T04B25</b>
	<b>TSM-T4-018</b>	<b>JOHN DEERE</b>	<b>408105-0100</b>	<b>T04B31</b>

	<b>TSM-T4-020</b>	<b>PERKINS TRACTOR, TRUCK T6.354.3 PERKINS F4</b>	<b>408105-0068 465960-0006 2674358/2674364</b>	<b>T04B58 T04B71</b>
	<b>TSM-T4-024</b>	<b>VOLVO PENTA / EARTH MOVING</b>	<b>408105-0259</b>	<b>T04E10</b>
	<b>TSM-T4-027</b>	<b>MB OM366</b>	<b>408105-0322</b>	<b>T04E66</b>
	<b>TSM-T4-029</b>	<b>PERKINS F2/F4 T6-354-4</b>	<b>465154-0011 2674365</b>	<b>T04B58 T04B54 T04B71</b>
	<b>TSM-T4-033</b>	<b>PERKINS</b>	<b>409860-0001 2674353 408105-0052</b>	

	<b>TSM-T4-040</b>	<b>NAVISTAR BUS / TRUCK DT466E AR.50</b>	<b>408105-0307 408105-0278</b>	<b>T04E17</b>
	<b>T4-TSM-NAV</b>	<b>NAVISTAR AR.50 7A 170-175 HP</b>		<b>T04E17</b>
	<b>TSM-T4-042</b>	<b>DAEWOO</b>	<b>447450-0137</b>	<b>T04E55</b>
	<b>TSM-T4-043</b>	<b>KOMATSU / VOLVO</b>	<b>447450-0084 465044-0234</b>	<b>T04B59</b>
	<b>TSM-T4-044</b>	<b>JOHN DEERE TRACTOR 8560 6466T</b>	<b>465355-0011 RE58420 EN BORGWARNER ES UN S2BS033</b>	<b>T04E45</b>
	<b>TSM-T4-048</b>	<b>MERCEDES BENZ</b>	<b>408105-0287</b>	<b>T04E66</b>

	<b>TSM-T4-052</b>	<b>SCANIA TRUCK / RABA MAN / DETROIT DIESEL</b>	<b>408105-0417 1317655 466616-0011</b>	<b>T04E06 T04E38 T04E02</b>
	<b>TSM-T4-053</b>	<b>KOMATSU / TRUCK / VARIOS / PERKINS F2 / F4 CON CUERDA</b>	<b>447450-0084 6135-81-8201 465044-0229</b>	<b>T04B59 T04B58</b>
	<b>TSM-T4-059</b>	<b>KOMATSU</b>	<b>447450-0261</b>	<b>T04B59</b>
	<b>TSM-T4-062</b>	<b>PERKINS VARIOS T6.60</b>	<b>466828-0010 2674A109 408105-0280</b>	<b>TB4131</b>
	<b>TSM-T4-065</b>	<b>FIAT AGRICULTURA / TRACTO / IVECO 1.90E, 190.38</b>	<b>465468-0006 4732533</b>	<b>T04B05</b>
	<b>TSM-T4-074</b>	<b>MERCEDES BENZ OM355</b>	<b>466646-0041</b>	<b>TB2556 T04E66</b>
	<b>TSM-T4-081</b>	<b>NAVISTAR BUS / TRUCK DT466E AR.60</b>	<b>408105-0307 408105-0278</b>	<b>T04E17</b>
	<b>TSM-T4-082</b>	<b>PERKINS AGRICULTURAL T6.60 / VOLVO</b>	<b>447450-0106 2674A080 466588-0009</b>	<b>T04E35</b>
	<b>TSM-T4-102</b>	<b>KOMATSU S6D105 ACEITE</b>	<b>447450-0086 465044-0257 6138-82-8201</b>	<b>T04B59</b>



	<b>TSM-T4-124</b>	<b>FORD TW15 401DT</b>	<b>465218-0006</b>	<b>T04B09</b>
	<b>TSM-TA51-003</b>	<b>VOLVO TRUCK F12 6.0L</b>	<b>441398-0036</b>	<b>TA5102 TA5104 TA5112</b>
	<b>TSM-TD02-001</b>	<b>PEUGEOT PARTNER MITSUBISHI 1.6HDI</b>	<b>49173-08750 9670371380</b>	<b>TD025S</b>
	<b>TSM-TD02-004</b>	<b>VW GOLF SEAT LEON TSI 1.4L</b>	<b>49373-08000 03C145701J</b>	<b>TD025M</b>
	<b>TSM-TD02-007</b>	<b>PEUGEOT PARTNER 1.6L</b>	<b>49373-09001</b>	<b>TD025</b>
	<b>TSM-TD02-013</b>	<b>SMART FORTWO-0.7L 61HP</b>	<b>19016387</b>	<b>TDO25M1</b>
	<b>TSM-TD02- 014BR</b>	<b>VW GOLF MK7 / AUDI A3 / SEAT LEON 1.4 TSI REVERSE BILLET</b>	<b>49180-08100 04E145713N</b>	<b>TD025 TD025M2</b>
	<b>TSM-TD02-016</b>	<b>KUBOTA AGRICULTURA INDUSTRIAL</b>	<b>49173-08200 1A024-1701A</b>	<b>TD025</b>

	<b>TSM-TD02-025BR</b>	<b>VW GOLF MK7 TSI BILLET</b>	<b>49795-97601 04E1457157</b>	<b>TD025I4BR</b>
	<b>TSM-TD02-028B</b>	<b>HONDA CR-V / CIVIC 1.5T BILLET</b>	<b>49373-07012</b>	<b>TD025M TD025</b>
	<b>TSM-TD03-002</b>	<b>FORD TRANSIT PUMA / RANGER 2.2</b>	<b>49131-08610 6C1Q-6K682-CD</b>	<b>TD03 TD03L4</b>
	<b>TSM-TD03-003</b>	<b>VOLVO TWIN S80 T6 / XC90 T6 2.8</b>	<b>49131-08210 49131-05101</b>	<b>TD03 TD03-08G</b>
	<b>TSM-TD03-005</b>	<b>BMW TWIN 2006/2010 335i DERECHO AGUA</b>	<b>49131-08700</b>	<b>TD03</b>
	<b>TSM-TD03-007</b>	<b>BMW TWIN TURBO 2006-2010 335i CI IZQUIERDO AGUA</b>	<b>49131-08911</b>	<b>TD03</b>
	<b>TSM-TD03-008</b>	<b>VOLVO TWIN S80 T6 / XC90 2.8</b>	<b>49131-08200 49131-05001</b>	<b>TD03</b>
	<b>TSM-TD03-010</b>	<b>BOBCAT / KUBOTA / IVECO / AGRICULTURA / MITSUBISHI</b>	<b>49131-05500</b>	<b>TD03</b>
	<b>TSM-TD03-016</b>	<b>KUBOTA MARINE 5.250 TDI, TRACTOR, INDUSTRIAL / MITSUBISHI</b>	<b>49131-08000 49131-08041</b>	<b>TD03-06G-3.3</b>
	<b>TSM-TD04-003</b>	<b>KUBOTA INDUSTRIAL / MITSUBISHI FUSO</b>	<b>49177-03130</b>	<b>TD04-12T</b>

	<b>TSM-TD04-009 * TSM-TD04-009- C</b>	<b>OPEL / VECTRA / SAAB 9-3 9-5 15T 2.3L</b>	<b>49189-08525</b>	<b>TD04 TD04HL</b>
	<b>TSM-TD04-010</b>	<b>VOLVO V70, S60 T5 N2P23HT</b>	<b>49189-08535 8658097</b>	<b>TD04HL TD04HL-16T</b>
	<b>TSM-TD04-018</b>	<b>VOLVO S80 / V70 / XC70 XC90 / S60 2.3 B2234T</b>	<b>8658098 49189-05200</b>	<b>TD04HL-13T</b>
	<b>TSM-TD04-016</b>	<b>SUBARU IMPRESA / FORESTER</b>	<b>466856-0003 464224102</b>	<b>TD04L</b>
	<b>TSM-TD04-022</b>	<b>STRATUS / CIRRUS 1G 2.4 VOLVO S40 1.9 XC70- 7XC90 2.5</b>	<b>49377-08300 36650634</b>	<b>TD04 TD04-14T</b>
	<b>TSM-TD04-022- 2G</b>	<b>STRATUS / CIRRUS 2G SEGUNDA GENERACION</b>	<b>CON 3 TORNILLOS</b>	<b>TD04 2G</b>
	<b>TSM-TD04-024</b>	<b>ISUZU MARINE , HITACHI / MITSUBISHI MAROOKA, CONSTRUCTION</b>	<b>49189-08100</b>	<b>TD04HL</b>
	<b>TSM-TD04-026</b>	<b>IVECO DAILY 7 PEUGEOT , CITROEN, JUMPER, DUCATO, BOXER</b>	<b>49377-08900</b>	<b>TD04L-14T</b>
	<b>TSM-TD04-AMD- TSM</b>	<b>DEUTZ GENERATOR 2.0 65KW</b>	<b>49377-07720</b>	<b>TD04-08T/6</b>
	<b>TSM-TD04-034</b>	<b>VOLVO s40 s60 v70 s80 2.0T 160 HP</b>	<b>49377-06050 8627989</b>	<b>TD04L TD04L-12T</b>
	<b>TSM-TD04-036</b>	<b>DODGE NEON SRT4 / PT CRUISER GT</b>	<b>49377-09120</b>	<b>TD04LR</b>

	<b>TSM-TD04-037</b>	<b>VOLVO / SAAB / RENAULT / LAGUNA 9.3</b>	<b>49377-08306 36650634</b>	<b>TD04 TD04-14T</b>
	<b>TSM-TD04-038</b>	<b>RENAULT LAGUNA MEGANE 2.0</b>	<b>8200396687 49377-07300 49377-08350</b>	<b>TD04 TD04TS-10T- 8.5</b>
	<b>TSM-TD04-039</b>	<b>IVECO PEUGEOT CITROEN FIAT DUCATO BOXER JUMPER 3.0L</b>	<b>49189-09160</b>	<b>TD04HL</b>
	<b>TSM-TD04-040</b>	<b>CHRYSLER SPIRIT SHADOW LEBARON NEW YORKER / MITSU</b>	<b>49183-01090 4556026</b>	<b>TE04H TE04H-13</b>
	<b>TSM-TD04-046</b>	<b>IVECO 3.0L</b>	<b>49389-04500 504340179</b>	<b>TD04HL TD04HL-13T- 6.0</b>
	<b>TSM-TD04-047</b>	<b>HYUNDAI GENESIS THETA</b>	<b>49377-06902</b>	<b>TD04L</b>
	<b>TSM-TD04-050</b>	<b>KOMATSU EXCAVATOR</b>	<b>49177-08540 49337-01610</b>	<b>TD04L</b>

	<b>TSM-TD04-051</b>	<b>CALIVER SR-T4 2.4</b>	<b>49189-07220</b>	<b>TD04HL4S</b>
	<b>TSM-TD04-054</b>	<b>BMW X3 125i F20 2010 (REVES)</b>	<b>49477-02011 MFD 49477-02006 7588.938</b>	<b>TD04LR6</b>
	<b>TSM-TD04-059</b>	<b>KUBOTA CONSTRUCCION INDUSTRIAL</b>	<b>49189-02710</b>	<b>TD04HL</b>
	<b>TSM-TD04-062</b>	<b>KIA SPORTAJE / HYUNDAI SONATA</b>	<b>49591-14381 90142-01030 90142-01031</b>	<b>TD04HL4S</b>
	<b>TSM-TD04-066</b>	<b>KOMATSU / CONSTRUCCION / EXCAVADOR</b>	<b>49177-08501 6205-81-8270</b>	<b>TD04-10T</b>
	<b>TSM-TD04-067</b>	<b>KUBOTA TRACTOR EARTH MOVING</b>	<b>49177-03190 49177-03180</b>	<b>TD04L4</b>
	<b>TSM-TD04-073</b>	<b>GM LNF CADILLAC ATC</b>	<b>49377-07831 12663028</b>	<b>TD04L6-04H</b>
	<b>TSM-TD04-074</b>	<b>KUBOTA</b>		<b>TD04HL-L3G TD04H</b>
	<b>TSM-TD04-076</b>	<b>MITSUBISHI FUSO CAMION , AUTOBUS</b>	<b>ME228854 ME223610 MFD 49389-02070 131209004 <del>49389-02042</del></b>	<b>TD04HL- 15MXK</b>
	<b>TSM-TD04-079</b>	<b>KUBOTA EARTH MOVING V3800</b>	<b>49189-00910</b>	<b>TD04HL-13G</b>
	<b>TSM-TD04-081</b>	<b>VOLVO S40 T4 1.9L</b>	<b>8627991 1490160</b>	<b>TD04</b>

	<b>TSM-TD04-091</b>	<b>KOMATSU / CONSTRUCCION S4D95L</b>	<b>49177-08500 49377-01500</b>	<b>TD04-10T</b>
	<b>TSM-TD04-109</b>	<b>BILLET BMW PASSENGER CAR 2.0T BMW 320i B48B20</b>	<b>49477-02454 49477-09211 49797-94201 16030900143 49477-02209</b>	<b>TD04 TD04LR6W</b>
	<b>TD04-TSM-02- MX</b>	<b>KIA / HYUNDAI / SANTA FE, SPORT / SONATA 2.0L</b>	<b>28231-2GTA1 90124-01050</b>	<b>TD04LG-13</b>
	<b>TSM-TD04-VG2</b>	<b>VW CRAFTER 2.5</b>	<b>49377-09044 076145702A</b>	<b>TD04L- 413TBSVG</b>
	<b>TSM-TD04-VG6</b>	<b>ACURA RDX HONDA MDX</b>	<b>49389-01040 49389-08215</b>	<b>TD04HL- 15TK31</b>
	<b>TSM-TD04- VG10</b>	<b>VW CRAFTER</b>	<b>49377-09701 076145701Q</b>	<b>TD04L4 TD04L4- 10TK3155-VG</b>
	<b>TSM-TD05-005</b>	<b>ALFA ROMERO 164 2.0T</b>	<b>49178-07300 49178-07200</b>	<b>TD05H-12B/6</b>
	<b>TSM-TD06-005</b>	<b>CAT 3066T EXCAVATOR 320 / 320B / 312 HYUNDAI 320C</b>	<b>49179-02260 49179-02280</b>	<b>TD06H</b>
	<b>TSM-TD06-006</b>	<b>CAT EXCAVATOR E200B HXS</b>	<b>51-5015 49179-00450</b>	<b>TD06H-14C</b>
	<b>TSM-TD07-000</b>	<b>mitsubishi 6D16T FUSO</b>	<b>49187-08070</b>	<b>TD07S-25A/13</b>
	<b>TSM-TF035-006</b>	<b>H100 VAN 2.5 MITSUBISHI</b>	<b>49135-08025 28200-4A160</b>	<b>TF035HM</b>


