



# TURBOS COMPLETOS NUEVOS CATÁLOGO 2021

CÓDIGO E&E	DATO TÉCNICO	NÚMERO DE PARTE	MODELO
TSM-TURBO BW004-1	DAF TRUCK MX300, MX400 408HP	1387-970-0004 1387-970-0009 1387-970-0030 1679178	B3G
TSM-TURBO- BW035-P	CATERPILLAR BULLDOZER C9 9L 210HP	175183 1274-988-0058 252-5165	B2G
TSM-TURBO G007	RENAULT TRAFIC 1.9	703245-0001	GT1549S
TSM-TURBO G013	RENAULT ESPACE, LAGUNA, MEGANE / VOLVO S40, V40	708639-0002 708639-0003	GT1749V
TSM-TURBO G015	AUDI A4, A6 / VW PASSAT TDI /	717858-0009 038145702N	GT1749V
TSM-TURBO G018- 1	M.B SPRINTER OM611	709836-0001 A6110960899	GT1852V
TSM-TURBO G053	MAZDA 3, MINNI COOPER, FORD C- MAX/MONDEO / CITROEN PICASSO	753420-0002 750030-0002	GT1544V
TSM-TURBO G069	ISUZU 4HE1XS NQR ELF BUS TRUCK N	700716-0001	GT2560S

<b>TSM-TURBO G071-1</b>	<b>SMART FORTWO M160</b>	<b>724961-0001 724961-0002</b>	<b>GT1238S</b>
<b>TSM-TURBO G083</b>	<b>HYUNDAI H100 CARGA / REDILAS / CARGA</b>	<b>715924-0001</b>	<b>GT1749S</b>
<b>TSM-TURBO G135</b>	<b>CHEVROLET 1.4 CRUZE, TRAX, SONIC BUICK ENCORE</b>	<b>781504-0001</b>	<b>MGT1446MZGL</b>
<b>TSM-TURBO G136</b>	<b>FORD TRANSIT TRACCIÓN IZQUIERDA</b>	<b>787556-0016</b>	<b>GTB1749VK</b>
<b>TSM-TURBO G152</b>	<b>CATERPILLAR 3304</b>	<b>409410-0006</b>	<b>T04B91</b>
<b>TSM-TURBO G196</b>	<b>SPRINTER VAN OM642</b>	<b>761154-0003</b>	<b>GTA2056VK</b>
<b>TSM-TURBO-G229-M</b>	<b>FIAT GRANDE PUNTO ABARTH 1.4</b>	<b>55238189 799502-0001 55219660</b>	<b>MGT1446GLSZ</b>
<b>TSM-TURBO-G270-1-P</b>	<b>PERKINS 1004-4L</b>	<b>2674A076 466674-0005</b>	<b>TA3123</b>
<b>TSM-TURBO-G282-P</b>	<b>PERKINS JCV T4.40 4.0L</b>	<b>2674A153 466854-0001</b>	<b>TA3120</b>
<b>TSM-TURBO-G581</b>			<b>TA2505</b>
<b>TSM-TURBO G-GT17-1</b>	<b>HYUNDAI H100 CARGA / REDILAS / CARGA</b>	<b>NUEVO GARRETT</b>	<b>GT1749S</b>

<b>TSM-TURBO G-GT37-1</b>	<b>POWER STROKE 6.0</b>	<b>NUEVO GARRET 743250-5025S</b>	<b>GT3782V</b>
<b>TSM-TURBO H001</b>	<b>CUMMINS TRACTOR, FORD CARGO 6CT</b>	<b>3522778</b>	<b>H1C</b>
<b>TSM-TURBO-H007</b>	<b>CUMMINS CASE INDUSTRIAL 6CTA</b>	<b>3536310 3536309</b>	<b>HX40W</b>
<b>TSM-TURBO H009</b>	<b>CUMMINS 6CT ISB 8.3</b>	<b>3590348</b>	<b>HX40W</b>
<b>TSM-TURBO-H086-P</b>	<b>CUMMINS ISM 11.0L / CUMMINS M11 PLUS</b>	<b>3590044 3800471 3780171</b>	<b>HX55</b>
<b>TSM-TURBO-H102</b>	<b>SCANIA TRUCK 124 DC12 420HP</b>	<b>4038613 4038617</b>	<b>HX55</b>
<b>TSM-TURBO I007</b>	<b>KUBOTA TRACTOR DIESEL</b>	<b>VA410152 / CK35</b>	<b>RHF3</b>
<b>TSM-TURBO I017-1</b>	<b>ISUZU EARTH MOVING</b>	<b>CIFK VB440051</b>	<b>RHF55</b>
<b>TSM-TURBO I052</b>	<b>ISUZU EXCAVATOR</b>	<b>VIDZ VB420076</b>	<b>RHF4H</b>
<b>TSM-TURBO-I063</b>	<b>VW GOLF 1.2 TSI CBZA - CBZB</b>	<b>03F145701F 03F145-701G</b>	<b>JHJ</b>
<b>TSM-TURBO I118</b>	<b>SUBARU IMPREZA WRX</b>	<b>VF37 VG440027</b>	<b>RHF55</b>

<b>TSM-TURBO-I171</b>	<b>YANMAR</b>	<b>12913718010 CY62 VC110033</b>	<b>RHB31</b>
<b>TSM-TURBO I151</b>	<b>ISUZU / JCB</b>	<b>CIBC VA720015</b>	<b>RHE61</b>
<b>TSM-TURBO K010</b>	<b>SEAT IBIZA CUPRA AUDI A3 VW JETTA BEETLE GOLF 1.8 180 HP</b>	<b>5303-970-0052</b>	<b>K03</b>
<b>TSM-TURBO K025</b>	<b>AUDI A3, VW GOLF 1.8T 150HP</b>	<b>5303-970-0011</b>	<b>K03</b>
<b>TSM-TURBO K031</b>	<b>MERCEDES BENZ OM904</b>	<b>5316-710-0012</b>	<b>K16</b>
<b>TSM-TURBO K032</b>	<b>RENAULT MASTER 2.5DCI</b>	<b>5303-970-0055</b>	<b>K03</b>
<b>TSM-TURBO K034</b>	<b>PEUGEOT 207 308 3008 5008</b>	<b>5303-970-0179</b>	<b>K03</b>
<b>TSM-TURBO K040</b>	<b>VW PASSAT ALHAMBRA SHARAN AUDI A4 1.8 150 HP</b>	<b>53039700029</b>	<b>K03</b>
<b>TSM-TURBO K043</b>	<b>VW EUROVAN / BORA 1.9 TDI</b>	<b>5439-710-8001</b>	<b>KP39</b>
<b>TSM-TURBO K051- 1</b>	<b>FORD / KLAND ROVER 2.0L ECOBOOST / VOLVO, PASSENGER 2.0</b>	<b>5303-970-0154 5303-710-0565 CB5E-6K682AB</b>	<b>K03</b>
<b>TSM-TURBO K061</b>	<b>VW GOLF TIGUAN GT 1.4 TSI 170HP</b>	<b>5303-970-0099</b>	<b>K03</b>

<b>TSM-TURBO K062</b>	<b>MAZDA CX7 2.3</b>	<b>5304-710-9904</b>	<b>K04</b>
<b>TSM-TURBO K064</b>	<b>GM DEUTZ OPEL INSIGNIA L850</b>	<b>5304-970-0059</b>	<b>K04</b>
<b>TSM-TURBO K067</b>	<b>AUDI A4 1.8 TFSI 2G EA888</b>	<b>5303-970-0123</b>	<b>K03</b>
<b>TSM-TURBO K109</b>	<b>NISSAN NAVARA PATHFINDER 2.5 DCI</b>	<b>5303-970-0210 5303-970-0337 5303-970-0182</b>	<b>BV45</b>
<b>TSM-TURBO K134</b>	<b>FORD ECOBOST MONDEO GALAXY LAND ROVER PASSENGER 2.0</b>	<b>5303-970-0368</b>	<b>K0NG</b>
<b>TSM-TURBO K179</b>	<b>NISSAN CARAVAN / NV350 2.5 DCI</b>	<b>5303-970-0268 5303-970-0341 5303-970-0373 5303-970-0709</b>	<b>BV40</b>
<b>TSM-TURBO M006</b>	<b>VOLVO, FORD PARTNER 1.6</b>	<b>49173-07502</b>	<b>TD025S2</b>
<b>TSM-TURBO M016</b>	<b>2007 HYUNDAI / KIA SANTA FE</b>	<b>49173-02401</b>	<b>TD025M</b>
<b>TSM-TURBO-M017</b>	<b>SUBARU FORESTER 2.0L / SUBARU IMPREZA</b>	<b>49377-04505 14412-AA4560</b>	<b>TD04L</b>
<b>TSM-TURBO M032</b>	<b>FORD TRANSIT 2.2L</b>	<b>49131-08610</b>	<b>TD03L4</b>
<b>TSM-TURBO M035</b>	<b>2011 FORD RANGER 2.2L</b>	<b>49131-06200</b>	<b>TD03L4</b>

<b>TSM-TURBO M046</b>	<b>VW GOLF , JETTA, TOURAN 1.4 TSI , AUDI A3, SEAT LEÓN TOLEDO</b>	<b>49373-01000</b>	<b>TD025M</b>
<b>TSM-TURBO-S013</b>	<b>NAVISTAR 7.6L (DE COPLE) DTA 466C</b>	<b>167336 1808749C91</b>	<b>S2E114 - BorgWarner T04E13-Garrett</b>
<b>TSM-TURBO T009</b>	<b>TOYOTA HILUX SW4 3.0L</b>	<b>17201-0L040 17201-30110</b>	<b>CT-VNT</b>
<b>TSM-TURBO-T013</b>	<b>TOYOTA HILUX PRADO FORTUNER 2.8L</b>	<b>1720-1-11080</b>	<b>CT-VNT CT16V</b>
<b>TSM-TURBO T015</b>	<b>TOYOTA HILUX INNOVA FOURTER 2G 2.4L</b>	<b>17201-11070</b>	<b>CT-VNT</b>
<b>TSM-TURBO G- TMF55-1</b>	<b>DETROIT DIESEL S.60 12.7 DDEC 3</b>	<b>466999-5001S</b>	<b>TMF55</b>