

# KITS DE REPARACIÓN



# CATÁLOGO 2021



<b>CÓDIGO E&amp;E / TSM</b>	<b>DATO TECNICO</b>	<b>P/N</b>	<b>MODELO</b>
TSM-RK-BW1-1	MAXX FORCE MAN BITURBO	1155-970-0000 1000-970-0128	B1G B1UG-R2S B1-R2S
TSM-RK-BW2-1	FORD INTERNATIONAL MAN BIT CARTUCHO CHICO	1000-970-0009 1270-970-0070 1270-001-1004	B2 / B2G B2V / B2US B2FS
TSM-RK-BW2-2	FORD INTERNATIONAL POWER STROKE 6.4 BITURBO	176010 176488 1263-970-0008	B2 / B2G B2V / B2US B2FS
TSM-RK-BW2-3	PERKINS / IVECO	1070-197-0002 1265-970-0000	B2 / B2G B2V / B2US B2FS
TSM-RK-BW2-4	INTERNATIONAL MAXXFORCE DT I334	1891392C93	B2FS
TSM-RK-BW2-5	INTERNATIONAL MAXXFORCE DT I334	1270-015-3502 1270-001-0014	B2NG
TSM-RK-BW2-6	MAXXFORCE, PERKINS	2674A256	B2 B2G

<b>TSM-RK-BW3-1</b>	<b>DAF NAVISTAR 12.9 MAXXFORCE BITURBO</b>	<b>1387-970-0003 1387-970-0066 1387-970-0035</b>	<b>B3</b>
<b>TSM-RK-BW3-2</b>	<b>FORD POWER STROKE 6.4 K29 BITURBO</b>	<b>1387-970-0003</b>	<b>B3 B3-V2S</b>
<b>TSM-RK-BW4-1R</b>	<b>BMW X6 X3 35i 535i 40i 335i</b>	<b>1853-710-0500</b>	<b>B03</b>
<b>TSM-RK-BW4-2</b>	<b>MERCEDES BENZ A CLASS 45 AMG M133</b>	<b>1855-710-0501</b>	<b>B03G</b>
<b>TSM-RK-BW5-1</b>	<b>MB OM924 LA EGR NUCLEO FIERRO</b>	<b>5316-970-0035</b>	<b>K24</b>
<b>TSM-RK-BW8-3R</b>	<b>VW POLO 2013 / AUDI A1 /S1 /SEAT 1.0 TSI BILLET</b>	<b>1633-970-0002 04C145701C 04C145702J</b>	<b>B01G</b>
<b>TSM-RK-B3G</b>	<b>DETROIT DIESEL SERIE 60 DDEC15</b>	<b>1322600108</b>	<b>B3G</b>
<b>TSM-RK-C1-1</b>	<b>JONH DEERE Y MAS</b>		<b>C14 C15</b>
<b>TSM-RK-C2-1</b>	<b>JONH DEERE Y MAS PORTANILLO GRANDE</b>		<b>K27 Y MAS</b>
<b>TSM-RK-C4-1</b>	<b>JONH DEERE Y MAS</b>		<b>C12 C13</b>

<b>TSM-RK-G1-2</b>	<b>LAND ROVER DISCOVERY / ROND. ESTRELLA C/PLATO</b>	<b>443854-0110</b>	<b>TB25 T25 GT28 T2 T250</b>
<b>TSM-RK-G2-5</b>	<b>PORTANILLOS 2 PARTES RONDANA DE MEDIA LUNA</b>		<b>T25 T28 T2</b>
<b>TSM-RK-G3-2</b>	<b>ISUZU PIZARRA- RONDANA DE ESTRELLA</b>	<b>430425-0059</b>	<b>TB28 T25 T2</b>
<b>TSM-RK-G4-5</b>	<b>PERKINS MERCEDES BENZ NAVISTAR JOHN DEERE CAT Y VARIOS</b>	<b>408105-0127</b>	<b>TB31 T04B TB34</b>
<b>TSM-RK-G4-5-1</b>	<b>KIT SE PARECE O SIMILAR A T04 VARIOS</b>		<b>TB31 TB34 T04</b>
<b>TSM-RK-G4-5-2</b>	<b>KIT DE PIZARRA</b>		<b>T04 / TB03</b>

<b>TSM-RK-G5-3-1</b>	<b>TRAFIC H100 MERCEDES PERKINS Y VARIOS</b>	<b>715924-0004</b>	<b>GT17-VNT GT20 GT15 GT17</b>
<b>TSM-RK-G5-3-2</b>	<b>APLICA AVARIOS PERKINS Y MAS</b>	<b>715924-0004</b>	<b>GT17-VNT GT15 GT20 GT22</b>
<b>TSM-RK-G5-3-3</b>	<b>FORD TRANSIT IZQUIERDO Y DERECHO</b>	<b>786880-0006</b>	<b>GT17 GT15 GTB1749V</b>
<b>TSM-RK-G5-6</b>			<b>GT1544S</b>
<b>TSM-RK-G8-1</b>	<b>PERKINS JOHN DEERE Y MAS</b>	<b>709147-0001</b>	<b>GT30 GT32 GT35</b>

<b>TSM-RK-G9-2</b>	<b>VOLVO, MERCEDES</b>		<b>GT42 GT45</b>
<b>TSM-RK-G9-3</b>	<b>SCANIA Y OTROS</b>	<b>779839-0025 779839-0026</b>	<b>GT45 GT4294S</b>
<b>TSM-RK-G10-2</b>	<b>S.60 DE PORTANILLO DD4 12 .7L PARA FLECHA LARGA</b>	<b>451888-0028</b>	<b>GT42 GT45</b>
<b>TSM-RK-G11-2</b>			<b>TA45 TA51</b>
<b>TSM-RK-G12-1</b>	<b>NGD DT466 DE PORTANILLO</b>	<b>449936-0002</b>	<b>GTA3782 GT37 GT40</b>
<b>TSM-RK-G13-1</b>	<b>PERKINS / CAT POTANILLO CHICO</b>	<b>433289-0195</b>	<b>GT22 GT22V</b>
<b>TSM-RK-G13-3</b>	<b>HINO</b>	<b>779144-0019 779144-0021</b>	<b>GT2263KLVN</b>
<b>TSM-RK-G13-4</b>	<b>TOYOTA COASTER N04C-4.0L</b>	<b>17201-E0740</b>	<b>GT2263KLVN</b>
<b>TSM-RK-G18-1</b>	<b>CATERPILLAR</b>	<b>465965-0002</b>	<b>TL92 TV92 TW94</b>

<b>TSM-RK-G19-1</b>	<b>SMART</b>	<b>727211</b>	<b>GTC12 GTC14</b>
<b>TSM-RK-G19-2</b>	<b>VW AMAROK 2.0 / SKODA OCTAVIA TDI / FORD MONDEO DV10C</b>	<b>785448-0003 806498-0001 795090-0003</b>	<b>GTB1449VZ GTC1459VZ GTC1446VMZ</b>
<b>TSM-RK-G19-3</b>	<b>TRANSPORTER 2.0 TDI</b>	<b>794097-0001 784844-0001</b>	<b>GT1446 GTB1244 GT1556V2</b>
<b>TSM-RK-G19-6</b>	<b>VW TOUAREG 3.0 TDI / AUDI / BMW</b>		<b>GTB2260VZK GTB2056VZ</b>
<b>TSM-RK-G19-7</b>	<b>LAND ROVER DISCOVERY</b>	<b>778401-0004</b>	<b>GT1444Z</b>
<b>TSM-RK-G19-9</b>	<b>PEUGEOT / DSGT</b>	<b>778087-0002</b>	<b>GT1446Z</b>
<b>TSM-RK-G19-13</b>	<b>FORD RANGER TDI Y MAS</b>	<b>822182-0004</b>	<b>GTD2060VZK</b>
<b>TSM-RK-G20-2</b>			<b>T04S</b>
<b>TSM-RK-G21-1</b>	<b>CATERPILLAR C15 3406</b>	<b>466807-0002</b>	<b>BTV85 / BTL75 GT50 / VTV75</b>

<b>TSM-RK-G21-2</b>	<b>CATERPILLAR C15 3406</b>	<b>471147-0007</b>	<b>GT50 / VTV75 BTV85 / BTL75</b>
<b>TSM-RK-G21-3</b>	<b>CATERPILLAR Y MAS</b>	<b>DE PIZARRA</b>	<b>BTV75/85/ UTV75</b>
<b>TSM-RK-G22-2</b>	<b>CATERPILLAR VARIOS</b>	<b>465679-0001 466428-0001</b>	<b>TV61 TV78 TV81</b>
<b>TSM-RK-G23-1</b>	<b>CAT C12 CON SEGUROS</b>	<b>GTA4294</b>	<b>GTA4294</b>
<b>TSM-RK-G23-2</b>	<b>CATERPILLAR</b>	<b>23528059</b>	<b>GTA4294</b>
<b>TSM-RK-G23-3</b>	<b>S. 60 DD4 4 12.7 DE SPACIADOR PARA FLECHA CORTA</b>	<b>712402-0007</b>	<b>GTA4294</b>
<b>TSM-RK-G24-1</b>	<b>SERIE 60 DDC5 / CATERPILLAR DE ANILLO ANCHO</b>	<b>720191-0086</b>	<b>GTA45V</b>
<b>TSM-RK-G24-2</b>	<b>VOLVO / CATERPILLAR / DAF</b>	<b>735059-0001 826098-0003</b>	<b>GTA4502</b>

<b>TSM-RK-G24-3</b>	<b>FALTA INFO</b>		<b>GTA45V</b>
<b>TSM-RK-G25-2</b>	<b>CATERPILLAR</b>	<b>704604-0003 739443-0003</b>	<b>GTA47 GTA55</b>
<b>TSM-RK-G25-2-2</b>	<b>CATERPILLAR C15 INDUSTRIAL GENERADOR</b>	<b>750525-0020</b>	<b>GTA50</b>
<b>TSM-RK-G25-3</b>	<b>CAT C15 DE PORTANILLO</b>	<b>PORTANILLO DOBLE</b>	<b>GTA55</b>
<b>TSM-RK-G25-4</b>	<b>CAT MTU Y MAS</b>	<b>725732-0006 756088-0008</b>	<b>GTA55</b>
<b>TSM-RK-G25-5</b>	<b>SCANIA / CAT Y MAS</b>	<b>715735-0013</b>	<b>GTA47</b>
<b>TSM-RK-G26-1</b>	<b>POWER STROKE 6.0</b>	<b>743250-0001</b>	<b>GTA3782VAS</b>
<b>TSM-RK-G26-2</b>	<b>GMC / CHEVROLET DUTY TRUCK</b>	<b>736554-0001 736554-0015</b>	<b>GTA3782VAS AVNT37</b>
<b>TSM-RK-G27-1</b>	<b>PARA TURBOS DE BALERO</b>		<b>GT25R / GT28R</b>
<b>TSM-RK-G27-2</b>	<b>PARA TURBOS DE BALERO</b>		<b>GT28R / GT30R</b>



<b>TSM-RK-G28-1</b>	<b>CATERPILLAR</b>	<b>466837-0001</b>	<b>UTV83 UTV8302</b>
<b>TSM-RK-G29-1 TSM-RK-G29-1-C</b>	<b>S.60 DD3 TMF</b>	<b>447807-0017</b>	<b>TV48 TMF</b>
<b>TSM-RK-G30-1</b>	<b>WAUKESHA</b>	<b>704837-0002</b>	<b>UTL94</b>
<b>TSM-RK-G32-1</b>	<b>CAT C13 CHECAR</b>	<b>BALERO</b>	<b>GT40R</b>
<b>TSM-RK-G34-1R</b>	<b>POWER 7.3</b>	<b>702011-0011</b>	<b>GTP38 TP38</b>
<b>TSM-RK-G34-2R</b>	<b>POWER 7.3 CON LIGAS</b>	<b>702011-0011</b>	<b>GTP38 TP38</b>
<b>RK-GT3571VA- TSM</b>	<b>POWER / NAVISTAR FORD F650 VT365 6.0</b>	<b>734852-5009S 734852-0004 184412C91 5C4Z-6K682</b>	<b>GT3571VA</b>

<b>TSM-RK-G40-1</b>	<b>NAVISTAR NGD DE ESPACIADOR</b>	<b>1836092C92</b>	<b>GTA37 GTA40</b>
<b>TSM-RK-G42-1</b>	<b>CUMMINS</b>		<b>T18A</b>
<b>TSM-RK-G44-1R</b>	<b>BMW X5M 4.4L-V8</b>		<b>MGT22</b>
<b>TSM-RK-G51-1</b>	<b>CAT C13 BITURBO</b>	<b>752538-0009</b>	<b>GTA4088BS</b>
<b>TSM-RK-G51-2</b>	<b>ISUZU</b>	<b>757654-0008</b>	<b>GTA4082KLNV</b>
<b>TSM-RK-G52-1</b>	<b>REVERSE ROTATION</b>	<b>817808-0011</b>	<b>MGT1446</b>
<b>TSM-RK-G56-1</b>	<b>CATERPILLAR D8K 583K D8H</b>	<b>6N7203 465032-0001 1P1163 488110-0004</b>	<b>T1238 / T1227</b>

<b>TSM-RK-H1-2</b>	<b>CUMMINS 4BT, 6BT VARIOS</b>	<b>3528771 3523322</b>	<b>H1C H1E WH1C WH1E</b>
<b>TSM-RK-H1-1</b>	<b>CUMMINS 4BT, 6BT VARIOS</b>	<b>3528771 3523322</b>	<b>H1C H1E WH1C WH1E</b>
<b>TSM-RK-H3-1</b>	<b>CUMMINS</b>	<b>3545653</b>	<b>H2B H2C H2D</b>
<b>TSM-RK-H3-2</b>	<b>CUMMINS</b>		<b>H2B H2C H2D</b>
<b>TSM-RK-H4-1</b>	<b>CUMMINS INDUSTRIAL</b>	<b>3545647</b>	<b>HC5A-HX82 HX80-HX85</b>
<b>TSM-RK-H4-2</b>	<b>CUMMINS INDUSTRIAL</b>		<b>HX80 / HX82 / HC5A</b>
<b>TSM-RK-H6-4</b>	<b>CUMMINS VARIOS</b>	<b>3537233</b>	<b>HX30W HX35W HX40W</b>

<b>TSM-RK-H8-1</b>	<b>N14, CUMMINS 350 / 400</b>	<b>3801523</b>	<b>HT3B HT60</b>
<b>TSM-RK-H9-1</b>	<b>CUMMINS STRATUS Y MAS</b>	<b>49189-08505</b>	<b>HX25 HX27W TD04</b>
<b>TSM-RK-H11-2</b>	<b>CUMMINS L10 M11</b>		<b>HX50 HX50W H2E</b>
<b>TSM-RK-H12-1</b>	<b>CUMMINS ISX ISM</b>	<b>4027807</b>	<b>HX55 HX55W</b>
<b>TSM-RK-H12-2</b>	<b>ISM ISX</b>	<b>3580726</b>	<b>HX55 HX55W</b>
<b>TSM-RK-H13-1</b>	<b>CUMMINS ISX SIGNATURE 600HP</b>	<b>4043620 4090043</b>	<b>HX60 HX60W</b>

<b>TSM-RK-H14-1</b>	<b>CUMMINS ISL / VOLVO MACK Y MAS</b>	<b>4031440 4047231</b>	<b>HE431V HE431VT HE400VG HY40V</b>
<b>TSM-RK-H14-2</b>	<b>CUMMINS ISL / VOLVO MACK Y MAS</b>	<b>4031440 4047231</b>	<b>HE431V HE431VT HE400VG HY40V</b>
<b>TSM-RK-H15-1</b>	<b>IVECO SIN RETENES</b>	<b>4031455</b>	<b>HY55V</b>
<b>TSM-RK-H15-2</b>	<b>IVECO SIN RETENES</b>	<b>4031455</b>	<b>HY55V</b>

<b>TSM-RK-H16-1</b>	<b>DETROIT S.60 - DD6 / CUMMINS ISM PACCAR MX-13</b>	<b>4032255</b>	<b>HE531VE HE531V</b>
<b>TSM-RK-H16-2</b>	<b>CUMMINS ISX DE VALVULA MECANICA</b>		<b>HE551V</b>
<b>TSM-RK-H17-1</b>	<b>CUMMINS ISX 450HP VASTAGO DELGADO</b>		<b>HE500VG HE561VE</b>
<b>TSM-RK-H17-2</b>	<b>CUMMINS ISX 450HP VASTAGO DELGADO</b>		<b>HE500VG HE561VE</b>

<b>TSM-RK-H17-3</b>	<b>CUMMINS ISX VASTAGO GRUESO</b>		<b>HE561VE</b>
<b>TSM-RK-H17-4</b>	<b>CUMMINS VASTAGO GRUESO CON RETENES</b>		<b>HE561VE</b>
<b>TSM-RK-H18-1</b>	<b>PACCAR PX6 / CUMMINS EGR RAM, CUMMINS 6.7</b>		<b>HE300VG HE351VE HE341VE</b>
<b>TSM-RK-H18-2</b>	<b>PACCAR PX6 / CUMMINS EGR RAM, CUMMINS 6.7</b>		<b>HE351VE HE300VG</b>

<b>TSM-RK-H18-2M</b>	<b>CUMMINS EGR CON RETENES</b>	<b>MELLET</b>	<b>HE351VE HE300VG</b>
<b>TSM-RK-H20-1</b>	<b>DODGE RAM ISB 6.7</b>	<b>5727046 5326057 3798538 5326058</b>	<b>HE300VG</b>
<b>TSM-RK-H22-1</b>	<b>CUMMINS ISX PORTANILLO SECCIONADO</b>		<b>HE531VE HE561VE</b>
<b>TSM-RK-H22-2</b>	<b>DETROIT S.60 - DD6 / CUMMINS ISM PACCAR MX-13</b>		<b>HE531VE</b>



<b>TSM-RK-H23-1</b>	<b>CUMMINS ISX15 / X15 PORTANILLO SECCIONADO DOS ANILLOS</b>	<b>3796349 3796389 3773561 3773562</b>	<b>HE400VG HE451VE</b>
<b>TSM-RK-H24-1</b>	<b>CUMMINS</b>	<b>3545662</b>	<b>HC3B / H3B</b>
<b>TSM-RK- HE400VG</b>	<b>CUMMINS ISM M11 EGR Y MAS</b>	<b>3774623 3774637</b>	<b>HE400VG</b>
<b>TSM-RK-I1-1</b>	<b>ISUZU SHIBAURA YANMAR MARINO</b>	<b>NN139922A</b>	<b>RHB51/RHB52</b>
<b>TSM-RK-I1-2</b>	<b>YANMAR MARINO</b>	<b>NN139921A 129474-18000</b>	<b>RHB52</b>
<b>TSM-RK-I2-1</b>	<b>CHEVROLET GMC GM1 GM2 GM3 GM4 GM5 GM6GM7 GM8</b>	<b>553T-559</b>	<b>RHC6</b>

<b>TSM-RK-I2-2</b>	<b>HINO / YANMAR / ISUZU</b>	<b>NZ854798 VX53 VX55 VX83 MYDA</b>	<b>RHC6</b>
<b>TSM-RK-I3-1</b>	<b>MARINO Y MAS ISUZU</b>		<b>RHB7 RHC7</b>
<b>TSM-RK-I5-1</b>	<b>VW TIGUAN AUDI SUBARU / ISUZU</b>	<b>APLICACIÓN VARIOS</b>	<b>RHF5 RHF5V JH5 VF40</b>
<b>TSM-RK-I6-1</b>	<b>NISSAN NP300 CABSTAR MERCEDES BENS MAZDA</b>	<b>VJ30 VIDZ KT10-1B VN3 / VN4</b>	<b>RHF4H</b>
<b>TSM-RK-I6-2</b>	<b>NISSAN SHIBAUARA NEW HOLLAND / AGRICULTURAL N844L</b>	<b>AS12 VN3 VB14 VB17 VB19</b>	<b>RHF4H RHF4</b>
<b>TSM-RK-I6-3</b>	<b>L200 / W200</b>	<b>VT10 VT11 VV11 VV13 VV17</b>	<b>RHF4V</b>
<b>TSM-RK-I6-4</b>	<b>SPRINTER VITTO</b>	<b>VV14</b>	<b>RHF4</b>

<b>TSM-RK-I7-1</b>	<b>USO MSARINO Y MAS</b>		<b>RHB6</b>
<b>TSM-RK-I8-2</b>	<b>FIAT PUNTO III1.9 JTD / KUBOTA TRACTOR- EXCAVATOR / SUZUKI LIANA 1.4</b>	<b>VL20 / CK27 VVP2 / VB34 CK30 / CK35</b>	<b>RHF3H RHF3</b>
<b>TSM-RK-I11-1</b>	<b>MERCEDES BENZ VITO OM646</b>	<b>VV19 / VV20</b>	<b>RHF4V</b>
<b>TSM-RK-I13-1</b>	<b>ISUZU 700P, NQR 75L / SUBARU IMPREZA WRX, 2.0L</b>	<b>VF30, VF39, VF35, VF43, VF48, VF52, VIFG, VIFH, VIET</b>	<b>RHF55 RHF55V</b>
<b>TSM-RK-I18-1</b>	<b>ISUZU</b>	<b>VZ9 / VZ21 / VZ27</b>	<b>RHB3</b>
<b>TSM-RK-I22-1</b>	<b>HINO TRUCK P11CT</b>	<b>VXBW VXBT VIHI</b>	<b>RHE7</b>
<b>TSM-RK-I22-2</b>	<b>ISUZU / HINO</b>	<b>VIBM VICK</b>	<b>RHE7</b>
<b>TSM-RK-I23-1</b>	<b>ISUZU TROOPER / ROND. 3/4 LUNA</b>	<b>VIBF</b>	<b>RHF5</b>
<b>TSM-RK-I24-1</b>	<b>ISUZU D-MAX 3.0 CRD / BUJE LARGO</b>	<b>VIEZ VT12 VT13</b>	<b>RHF5V</b>
<b>TSM-RK-I26-1</b>	<b>ISUZU TRUCK 6WG1</b>	<b>VIE00912</b>	<b>RHG8</b>

<b>TSM-RK-I27-1</b>	<b>VW, MK27 / AUDI / SEAT 2.0</b>	<b>06H145702L</b>	<b>JH5 JHJ</b>
<b>TSM-RK-I31-1R</b>	<b>VW JETTA, PASSAT 1.4L BILLET REVERSE</b>	<b>04E145721F RHF3-035</b>	<b>RHF3 JHJ</b>
<b>TSM-RK-K02-1</b>	<b>KOMATSU</b>	<b>6506-21-5920</b>	<b>KTR110G</b>
<b>TSM-RK-K1-1</b>	<b>NORMALES</b>	<b>5303-711-0000</b>	<b>K03 K04</b>
<b>TSM-RK-K1-2</b>	<b>SPRINTER VW BORA MAZDA Y MAS</b>	<b>5303-711-0001</b>	<b>K03 K04</b>
<b>TSM-RK-K1-3</b>	<b>VW CRAFTER</b>	<b>5303-711-0001</b>	<b>K03 K04-R2S</b>
<b>TSM-RK-K2-2</b>	<b>VW SEAT AUDI Y MAS</b>		<b>K03 K04</b>

<b>TSM-RK-K3-3</b>	<b>MERCEDES 904</b>	<b>5316-970-7123</b>	<b>K14 K16</b>
<b>TSM-RK-K4-2</b>	<b>MERCEDES BENZ OM904LA</b>	<b>5316-711-0002 5316-970-7132</b>	<b>K16</b>
<b>TSM-RK-K6-4</b>	<b>MERCEDES 906 / 926</b>	<b>5327-970-7201</b>	<b>K27</b>
<b>TSM-RK-K8-1</b>	<b>MAN TRUCK D2066LF SIN PLATO Y ESPACIADOR PORTANILLO</b>	<b>172743</b>	<b>K31</b>
<b>TSM-RK-K10-1</b>		<b>5331-711-0504 5336-711-0026 5434-711-0000</b>	<b>K36 / K37</b>
<b>TSM-RK-K13-1</b>	<b>VW EUROVAN TDI 1.9Y MAS</b>	<b>5303-711-0001</b>	<b>KP39 KP35</b>

<b>TSM-RK-K13-2</b>	<b>VW JETTA TDI 1.9 Y MAS</b>		<b>KP35 KP39</b>
<b>TSM-RK-K13-4</b>	<b>MERCEDES BENZ SPRINTER</b>		<b>BV39 KP39</b>
<b>TSM-RK-K13-5</b>	<b>AMAROK CRAFTER / M.B / VW VENTO</b>		<b>KP39 / KP35 R2S-KP35 R2S-KP39</b>
<b>TSM-RK-K16-1</b>	<b>USO MARINO INDUSTRIAL</b>	<b>5337-771-0003</b>	<b>K37</b>
<b>TSM-RK-K17-1</b>	<b>PORTANILLO ESPACIADOR CORTO</b>	<b>5331-711-0005</b>	<b>K29 K31</b>
<b>TSM-RK-K17-2</b>	<b>VOLVO PENTA MARINE</b>	<b>5331-711-0505 5331-970-6704 5331-970-6714 5331-970-6718</b>	<b>K31</b>

<b>TSM-RK-K18-1</b>	<b>VW BORA SEAT AUDI</b>		<b>BV43 K03</b>
<b>TSM-RK-K18-4</b>	<b>JETTA 2.0 TDI / URVAN NV350 2.5L</b>	<b>5303-970-0210 1000-970-0057</b>	<b>BV40 BV43</b>
<b>TSM-RK-K19-1</b>	<b>PORTANILLO ALTO</b>		<b>KP35 KP39</b>
<b>TSM-RK-M1-1</b>	<b>SPIRIT SHADOW PHANTOM NEW YORKER LEBARON</b>	<b>49189-08515</b>	<b>TD04 TC04</b>
<b>TSM-RK-M1-2</b>	<b>STRATUS CIRRUS / VOLVO / KOMATSU MALIBU / DUCATO SUBARU / VW CRAFTER / ACURA MDX/RDX SAAB / VECTRA Y VARIOS MAS</b>	<b>49189-08505</b>	<b>TD04LR6 TD04L HX25 HX27W</b>

<b>TSM-RK-M1-4</b>	<b>DODGE NEON SRT 4 2.4 / CHRYSLER PT CRUISER</b>	<b>49377-09120 49377-09110</b>	<b>TD04L TD04LR</b>
<b>TSM-RK-M3-1</b>	<b>CATERPILLAR Y MAS</b>	<b>49178-07300</b>	<b>TD05 TE06</b>
<b>TSM-RK-M3-2</b>	<b>CAT 320 Y MAS CON PLATO OVALADO</b>	<b>49179-08600</b>	<b>TD06</b>
<b>TSM-RK-M5-1</b>	<b>MITSUBISHI FUSO YANMAR ISUZU Y MAS</b>		<b>TD07 TD08</b>
<b>TSM-RK-M5-2* TSM-RK-M5-2-1</b>			<b>TD07</b>
<b>TSM-RK-M8-1</b>	<b>SMART FORTWO PEUGEOT PARTNER SUZUKI SWIFT VW 1.4L</b>	<b>49173-08770</b>	<b>TF025 TD025</b>



<b>TSM-RK-M8-2</b>	<b>TRANSIT VOLVO BMW PARTNER HONDA CIVIC VW SEAT</b>		<b>TF025 TD025 TD03</b>
<b>TSM-RK-M9-1</b>	<b>NISSAN JUKE- H100 VAGONETA</b>	<b>49135-09700</b>	<b>TF035</b>
<b>TSM-RK-S1-1</b>	<b>BOBCAT / JOHN DEERE</b>	<b>312942</b>	<b>S1A S1B</b>
<b>TSM-RK-S1-2</b>	<b>BOBCAT / JOHN DEERE</b>	<b>174925</b>	<b>S1A S1B S100</b>
<b>TSM-RK-S4-1</b>	<b>CATERPILLAR Y MAS</b>	<b>318380</b>	<b>S2B</b>
<b>TSM-RK-S5-1</b>	<b>CATERPILLAR / JOHN DEERE Y MAS</b>	<b>318378</b>	<b>S2B</b>

<b>TSM-RK-S6-1</b>	<b>CATERPILLAR DEUTZ MAN MACK SCANIA Y MAS</b>	<b>318386 318387</b>	<b>S3B</b>
<b>TSM-RK-S6-2</b>	<b>CATERPILLAR DEUTZ MAN MACK SCANIA Y MAS</b>	<b>170381</b>	<b>S3B</b>
<b>TSM-RK-S7-2</b>	<b>CATERPILLAR 3126 / MAXXFORCE Y JOHN DEERE</b>	<b>178179</b>	<b>S300 S300V110 S300V129 S300V</b>
<b>TSM-RK-S8-1</b>	<b>CATERPILLAR Y MAS</b>	<b>318396 318397</b>	<b>S400 S410</b>
<b>TSM-RK-S8-2</b>	<b>CATERPILLAR Y MAS</b>	<b>318396 318397</b>	<b>S400 S410</b>
<b>TSM-RK-S9-1</b>	<b>CATERPILLAR Y MAS</b>	<b>318368</b>	<b>3LM</b>
<b>TSM-RK-S10-1</b>	<b>SCANIA / VOLVO</b>	<b>3545659 3545660 3524840 318350</b>	<b>4LE</b>
<b>TSM-RK-S10-2</b>	<b>CATERPILLAR Y MAS</b>		<b>4LG / 4LF/4LG</b>

<b>TSM-RK-S11-1</b>	<b>DORMAN</b>	<b>3545674</b>	<b>4MF</b>
<b>TSM-RK-S13-1</b>	<b>CATERPILLAT Y MAS</b>	<b>166775</b>	<b>S2E</b>
<b>TSM-RK-S14-1</b>	<b>CAT 3126 / JOHN DEERE YMAS</b>	<b>17197 178186</b>	<b>S200</b>
<b>TSM-RK-S14-2</b>	<b>CAT 3126 / JOHN DEERE YMAS</b>		<b>S200</b>
<b>TSM-RK-S15-1</b>	<b>PERKINS / VOLVO / KOMATSU</b>	<b>318399 318398</b>	<b>S4T</b>
<b>TSM-RK-S16-1</b>	<b>CATERPILLAR Y MAS</b>		<b>S3 S3A</b>

<b>TSM-RK-S17-1</b>	<b>CATERPILLAR PERKINS Y MAS</b>	<b>318377</b>	<b>S2A</b>
<b>TSM-RK-S17-3</b>	<b>CATERPILLAR Y MAS</b>	<b>318614 318569 174735</b>	<b>S2A</b>
<b>TSM-RK-S18-1</b>	<b>PERKINS / CUMMINS</b>	<b>3545657 3534658</b>	<b>3LD</b>
<b>TSM-RK-S19-1</b>	<b>4MD / 4HD</b>	<b>183216 3545672 318359</b>	<b>4MD / 4HD</b>
<b>TSM-RK-S21-1</b>	<b>CATERPILLAR C9 Y MAS</b>	<b>176392</b>	<b>S310</b>

<b>TSM-RK-S22-1</b>	<b>CATERPILLAR</b>	<b>318405 318409</b>	<b>S4D</b>
<b>TSM-RK-T7-1</b>	<b>TOYOTA YARIS</b>	<b>17201-33010</b>	<b>CT2</b>
<b>TSM-RK-T8-1</b>	<b>TOYOTA HILUX 3.0L</b>	<b>17201-0L040</b>	<b>CT-VNT</b>
<b>TSM-RK-T9-1</b>	<b>TOYOTA HIACE / HILUX</b>	<b>17201-30030</b>	<b>CT16</b>
<b>TSM-RK-T11-1</b>	<b>TOYOTA PRADO / HILUX</b>	<b>17201-11080</b>	<b>CT-VNT</b>
<b>TSM-RK-TIL1-1</b>	<b>JACK 2.8L      CHINO</b>	<b>JK55X8002-09W JK55X8002-02-1</b>	<b>JK55</b>

<b>TSM-RK-150214</b>	<b>CUMMINS</b>		<b>ST50 / VT50</b>